PRESERVATION OF TOMBS OF SULTAN IBRAHIM & AMIR SULTAN MUHAMMAD, WHS MAKLI

1ST CONSULTATIVE COMMITTEE MEETING Folio XII– Consultative Committee Decisions



Assessment of Studies Undertaken

- 1. ID Introduction Folio
- 2. AD Architectural Drawings Folio
- 3. NS Unique Numbering System Folio
- 4. PD Photographic Documentation Folio
- 5. SD Superimposition Drawings Folio
- 6. DT Damage Assessment and Proposed Treatments Folio
- 7. MA Historic Brick Masonry Analysis Folio
- 8. MT Material Treatments & Guidelines Folio
- 9. CA Consultants' Assessment Folio



Cleaning Procedure Dry cleaning Graffiti Cleaning







Matching Brick Selection

Soils for Brick making

Size of Brick

Matching colour to historic

brick









Matching Mortar Selection
Internal and external
Supporting existing mortar









Floor (Internal and external) Treatment Sample flooring Extent of conservation Reuse and relaying of stone







Dome Treatment - External

Scaffolding

SS strips

Tension cables

Investigation
pits for
examining void
between domes






Dome Treatment - Internal

Scaffolding

SS strips

Tension cables

Investigation
pits for
examining void
between domes





Kashi Treatment

Extent of Conservation
Temp. support to historic tiles
Colors used
Design of tiles
Inscriptions Vs. Blank colored
tiles









Stucco Treatment

Supporting existing Stucco edges New stucco Extent of conservation works









Fresco Treatment

Existing Fresco observation

Direction for cleaning and restoration



Stone conservation - Fretwork and Extent

- Assessing Damage of prior intervention along East Façade fretwork
- Fretwork sample with terracotta/Chiroli
- Attachment of newly prepared piece with existing historic fretwork
- Replacing damaged stone
- Carving vs. plain stone
- Cenotaph conservation







Debris along South entrance chamber Clean up and stacking of Debris Conservation extent



