



16

98

GOVERNMENT OF SINDH
CULTURE, TOURISM &
ANTIQUITIES DEPARTMENT

NOTIFICATION

No. OSD/CHC/RBQ-01-49/2017: In exercise of the powers conferred by Sub-Section (1) of Section-6 of the Sindh Cultural Heritage (Preservation) Act, 1994, and on the recommendations of Advisory Committee on Sindh Cultural Heritage, the Culture, Tourism & Antiquities Department, Government of Sindh is pleased to declare the premises/buildings described below to be Protected Heritage within the meaning of the said Act.

(RAMBAGH QUARTER KARACHI)

S.NO.	NAME OF BUILDING	PLOT #	ADDRESS	REASON FOR ENLISTMENT AS HERITAGE
1.	Old Shahani Building	RB-3/ 8/ 1,	Teckchand Udhamdas Road;	Architectural Value
2.	Anubehar Building	RB-3/ 23/ 1,	D'mello Road;	Architectural Value
3.	Premkunj Building	RB-3/ 23/ 2/ 2,	Maulana Din Mohammad Wafai (Strachan) Road;	Architectural Value
4.	Alfalah Manzil	RB-3/ 23/ 2/ 1,	D'mello Road;	Architectural Value
5.	Naveen Mansion	RB-6/ 86,	Feroz Shah Street, Hormusji Street;	Architectural Value
6.	Pinjara Pure Building	RB-7/ 3,	Panjara Pure Road, M. A. Jinnah (Bunder) Road;	Architectural Value
7.	Haji Manzoor Building	RB-7/ 9,	Bhojraj Road, Ram Talao Road;	Architectural Value
8.	Afundi Manzil	RB-7/ 10/ 7,	Chand Bellaram Road, Ram Talao Road;	Architectural Value
9.	Karachi Mansion	RB-13-7/ 12,	M. A. Jinnah (Bunder) Road, Robson Road;	Architectural Value
10.	Ramkrishin/ Nawab Manzil	RB-7/ 20C,	Shahrah-e-Liaquat (Frere Road), Roop Chand Bellaram Road;	Architectural Value
11.	Khan Mansion	RB-7/ 22,	Sunder Das Road, Bhojraj Road;	Architectural Value

5/2/18

12.	KB Noori Building	RB-8/ 7/ 2/ 1,	M. A. Jinnah (Bunder) Road, Mohammad Bin Qasim (Burnes) Road;	Architectural Value
13.	Sugan Mansion	RB-9/ 2/ 1, 2/ 2, 2/ 3,	Mohammad Bin Qasim (Burnes) Road;	Architectural Value
14.	Saheli Mansion	RB-9/ 13,	Mohammad Bin Qasim (Burnes) Road, Robson Road;	Architectural Value
15.	Jamnadas Building	RB-9/ 18,	Jethamal Road, Jhamrai Road;	Architectural Value
16.	Moti Ram Building	RB-9/ 20,	Jhamrai Road, Amil Road;	Architectural Value
17.	Rais Manzil	RB-10/ 3,	Tirathdas Road, Assanmal Ojha Road;	Architectural Value
18.	Wazir Ali Building	RB-10/ 4,	Tirathdas Road, Assanmal Ojha Road;	Architectural Value
19.	Wazir Ashraf Building	RB-10/ 5/ 1,	Tirathdas Road, Assanmal Ojha Road;	Architectural Value
20.	New Lekhraj	RB-10/ 15,	Gidumal Lekhraj Road;	Architectural Value
21.	Old Lekhraj	RB-10/ 16,	Gidumal Lekhraj Road;	Architectural Value
22.	Muhammad Ali Building	RB-10/ 17,	Gidumal Lekhraj Road;	Architectural Value
23.	Mama Parsi Building	RB-10/ 19,	Babar (Ramchandra Temple) Road;	Architectural Value
24.	Bholchund Building	RB-10/ 20,	Babar (Ramchandra Temple) Road;	Architectural Value
25.	Kalavati Nivass	RB-11/ 1A, 2,	Mohan Road, Pahilraj Lilaram Road;	Architectural Value
26.	Ahmed Ali, Akber Ali Building	RB-11/ 1A, 3,	Mohan Road, Pahilraj Lilaram Road;	Architectural Value
27.	Asnand Khatori Building	RB-11/ 1A, 4,	Mohan Road, Pahilraj Lilaram Road;	Architectural Value
28.	Aziz Mehel	RB-11/ 1A, 5,	Mohan Road, Pahilraj Lilaram Road;	Architectural Value
29.	Narayan Gopal Building	RB-11/ 1C,	Babar (Ramchandra Temple) Road, Pahilraj Lilaram Road;	Architectural Value
30.	Shakeel Mansion/ Chaki Compound	RB-11/ 6, 7,	Babar (Ramchandra Temple) Road, Gwali Lane no. 1;	Architectural Value
31.	Government Boys Primary School	RI3-11/ 12,	Babar (Ramchandra Temple) Road, Gwali Lane no. 1;	Architectural Value
32.	Ramchandra Temple	RB-11,	Next To Plot 59, Babar (Ramchandra Temple) Road;	Architectural Value
33.	Burns Garden	RB-2,	Strachan Road, Shahrah-e- Kamal Atatürk (Kings Way), Dr. Ziauddin Ahmed (Kutchery) Road;	Architectural Value

for
8/3/18

34.	Pakistan Chowk	RB-5,	Strachan Road, Dr. Ziauddin Ahmed (Kutchery) Road;	Architectural Value
35.	Aram Bagh Park	R13-7/23,	Frere Road, Panjara Pure Road, Roop Chand Bellaram Road;	Architectural Value
36.	Sabri Chowk	RB-9,	M. A. Jinnah (Bunder) Road, Mohammad Bin Qasim (Burnes) Road;	Architectural Value
37.	Hindu Gymkhana (National Academy of Performing Art)	RB-1/ 5,	Sarwar Shaheed (Ingle) Road, Aiwan-e-Saddar (Havelock Road), Karachi	Architectural Value
38.	Old State Bank Building (Victoria Museum)	RB-2	Sarwar Shaheed (Ingle) Road, Karachi.	Architectural Value
39.	Shahab Mansion	RB-9/ 17,	Mohammad Bin Qasim (Burnes) Road, Jethmal Road, Karachi	Architectural Value
40.	Haroon Mansion	RB-9/ 16,	Mohammad Bin Qasim (Burnes) Road, Jhamrai Road, Karachi	Architectural Value
41.	Wasim Mansion	RB-9/ 15,	Mohammad Bin Qasim (Burnes) Road, Jhamrai Road, Karachi	Architectural Value
42.	Rooman Building	RB-9/ 22,	Tirathdas Road, Robson Road, Karachi	Architectural Value
43.	Sobhraj Chetumal Maternity Home	RB-10/ 26,	Tirathdas Road, Robson Road, Karachi	Architectural Value
44.	Sindh Wildlife Building	RB-1/ 3,	Aiwan-e-Saddar (Havelock Road), Maulana Din M. Wafai (Strachan) Road, Karachi	Architectural Value
45.	Y. M. C. A. Building	RB-1/ 2,	Aiwan-e-Saddar (Havelock Road), Maulana Din M. Wafai (Strachan) Road, Karachi	Architectural Value
46.	Muslim Gymkhana	RB-2	Dr. Ziauddin Ahmed (Kutchery) Road, Aiwan-e-Saddar (Havelock Road), Karachi	Architectural Value

Signature
08/2/18

47.	D. J. Sindh Government Science College Extension	RB-2	Mohammad Bin Qasim (Burnes) Road, Shahrah-e-Kamal Ataturk (Kings Way)	Architectural Value
48.	N. E. D University Old City Campus	RB-4/ 3 & 4,	Mohammad Bin Qasim (Burnes) Road, Maulana Din M. Wafai (Strachan) Road, Karachi	Architectural Value
49.	D. J College (Deyaram Jethmal College)	RB-4/ 3 & 4,	Dr. Ziauddin Ahmed (Kutchery) Road, Shahrah-e-Kamal Ataturk (Kings Way), Karachi	Architectural Value
50.	Geetumal (Giddu Mall) Building	RB-3/ 26,	Maulana Din M. Wafai (Strachan) Road, M. Bin Qasim (Burnes) Road, Karachi	Architectural Value
51.	Khan Enterprises/ DMD Trust Building	RB-3/ 22/ 2,	Maulana Din Mohammad Wafai (Strachan) Road, Karachi	Architectural Value
52.	Dr. Khan Building	RB-3/ 18/ 1,2	Maulana Din Mohammad Wafai (Strachan) Road, Karachi	Architectural Value
53.	Sarnagati Building	RB-5/ 7,	Maulana Din Mohammad Wafai (Strachan) Road, Arambagh Road, Karachi	Architectural Value
54.	P. K. Shahani Building	RB-5/ 6,	Hormusji Street, Dr. Ziauddin Ahmed (Kutchery) Road, Karachi	Architectural Value
55.	Badrudin Building	RB-5/ 5,	Hormusji Street, Arambagh Road, Karachi	Architectural Value
56.	Sitakunj Building	RB-5/ 3,	Hormusji Street, Arambagh Road, Karachi	Architectural Value
57.	Salika Company Building	RB-5/ 1, 3,	Dr. Ziauddin Ahmed (Kutchery) Road, Karachi	Architectural Value
58.	Sewa Kunj Hostel	RB-5/ 10,	Sharah-e-Liaquat (Frere Road), Karachi	Architectural Value
59.	Mendoza Building	RB-5/ 11,	Arambagh Road, Karachi	Architectural Value
60.	Raza Library Building	RB-7/ 20 A,	Sharah-e-Liaquat (Frere Road), Karachi	Architectural Value
61.	lucky Chambers	RB-7/ 20 B,	Sharah-e-Liaquat (Frere Road), Mohammad Bin Qasim (Burnes) Road, Karachi	Architectural Value
62.	Manzoor Sons Building	RB-7/ 19,	Mohammad Bin Qasim (Burnes) Road, Karachi	Architectural Value
63.	Jamila Nighat Maternity Home	RB-6/ 116,	Arambagh Road, Panjra Pure Road, Karachi	Architectural Value

8/2/18

64.	Hasan Manzil	RB-6/ 123,	Arambagh Road, Sharah-e-Liaquat (Frere Road), Karachi	Architectural Value
65.	Log Ram Building	RB-6/ 121,122	Arambagh Road, Panjra Pure Road, Karachi	Architectural Value
66.	Zainab Manzil	RB-6/ 98,	Sharah-e-Liaquat (Frere Road), Hormusji Street, Karachi	Architectural Value
67.	Saify Electric Trading Co.	RB-6/ 73,	Sharah-e-Liaquat (Frere Road), Yousuf Street, Karachi	Architectural Value
68.	Markaz-e-Ehl-e-Sunnat	RB-6/ 45,	Sharah-e-Liaquat (Frere Road), Yousuf Street, Karachi	Architectural Value
69.	Shams Light House Building	RB-6/ 15,	Dr. Ziauddin Ahmed (Kutchery) Road, Masjid Street, Karachi	Architectural Value
70.	Sadik Manzil	RB-6/ 107,	Feroz Shah Road, Arambagh Road, Karachi	Architectural Value
71.	Yousuf Manzil	RB-6/ 4	Abba Soomar Street, Karachi	Architectural Value
72.	Unknown	RB-6/ 3	Abba Soomar Street, Karachi	Architectural Value
73.	Abu Bakar Siddique Manzil	RB-6/ 1	M. A. Jinnah (Bunder) Road, Dr. Ziauddin Ahmed (Kutchery) Road, Karachi	Architectural Value
74.	Haji Ibrahim Building	RB-6/ 1	M. A. Jinnah (Bunder) Road, Abba Soomar Street, Karachi	Architectural Value
75.	Mollai (Bhagwani) Mansion	RB-6/ 18,	M. A. Jinnah (Bunder) Road, Abba Soomar Street, Karachi	Architectural Value
76.	Opal Building	RB-6/ 19,	M. A. Jinnah (Bunder) Road, Masjid Street, Karachi	Architectural Value
77.	Talpur Building	RB-6/ 74,	M. A. Jinnah (Bunder) Road, Karachi	Architectural Value
78.	Gul Trading Company Building	RB-6/ 83	M. A. Jinnah (Bunder) Road, Karachi	Architectural Value
79.	Coffee House (Wassumal) Building	RB-6/ 82,	M. A. Jinnah (Bunder) Road, Arambagh Road, Karachi	Architectural Value
80.	Sami Chambers	RB-6/ 108,	M. A. Jinnah (Bunder) Road, Arambagh Road, Karachi	Architectural Value
81.	Awan Lodge	RB-6/ 109,	Arambagh Road, Panjra Pure Road, Karachi	Architectural Value
82.	Sindh Zamindar Hotel	RB-7/ 4,	M. A. Jinnah (Bunder) Road, Bhojraj Road, Karachi	Architectural Value
83.	Zubaida Mansion	RB-8/ 1/ 1, 1/ 2,	M. A. Jinnah (Bunder) Road, Robson Road, Karachi	Architectural Value
84.	Dost Manzil	RB-8/ 4,	Robson Road, Mohammad Bin Qasim (Burnes) Road, Karachi	Architectural Value
85.	Wadhmal Deumal Panchayat Trust Building	RB-9/ 7,	Mohammad Bin Qasim (Burnes) Road, Karachi	Architectural Value

8/3/18

86.	Bhojraj Building	RB-10/ 1,	Babar (Ramchandra Temple) Road, Tirathdas Das Road, Karachi	Architectural Value
87.	Shikarpuri Mansion (Ceasor Building)	RB-10/ 8,	Assanmal Ojha Road, Gidumal Lekhraj Road	Architectural Value
88.	Darul-Ishaat (Tayyab Ali) Building	RB-10/ 9,	Babar (Ramchandra Temple) Road, Assanmal Ojha Road, Karachi	Architectural Value
89.	Hassan Ali (Lekhraj) Building	RB-10/ 18,	Babar (Ramchandra Temple) Road, Gidumal Lekhraj Road, Karachi	Architectural Value
90.	Bholchund Zehra Building	RB-10/ 24,	Robson Road, Gidumal Lekhraj Road, Karachi	Architectural Value
91.	Thakurdas Building (Zarina Manzil)	RB-10/ 23,	Robson Road, Gidumal Lekhraj Road, Karachi	Architectural Value
92.	Bhojaj Building	RB-10/ 21,	Babar (Ramchandra Temple) Road, Gidumal Lekhraj Road, Karachi	Architectural Value
93.	Sheikha Building	RB-10/ 10,	Babar (Ramchandra Temple) Road, Gidumal Lekhraj Road, Karachi	Architectural Value
94.	Ganga Ram Building	RB-10/ 11,	Gidumal Lekhraj Road, Assanmal Ojha Road, Karachi	Architectural Value
95.	Malkani Mansion	RB-10/ 12,	Gidumal Lekhraj Road, M. A. Jinnah (Bunder) Road, Karachi	Architectural Value
96.	Rehman Dental Clinic Building	RB-10/ 12A,	M. A. Jinnah (Bunder) Road, Babar (Ramchandra Temple) Road, Karachi	Architectural Value
97.	Azfar Mansion (Rehman Building)	RB-10/ 13,	M. A. Jinnah (Bunder) Road, Gidumal Lekhraj Road, Karachi	Architectural Value
98.	Thakurdas Building (Thakur Singh Building)	RB-10/ 14,	M. A. Jinnah (Bunder) Road, Karachi	Architectural Value
99.	Mukhi Wadhmal Building	RB-11/ 1A, 1,	M. A. Jinnah (Bunder) Road, Pahilraj Lilaram Road, Karachi	Architectural Value
100.	Government Veterinary Hospital (Richmond Crawford Dispensary)	RB-11/ 2/ 1,	M. A. Jinnah (Bunder) Road, Karachi	Architectural Value
101.	China Amersi Building	RB-12/ 14,	Rattan Street, Satsing Shivan Street, Karachi	Architectural Value
102.	Domed Structure	RB-12/ 14A,	Rattan Street, Satsing Shivan Street, Karachi	Architectural Value
103.	Qadeer Brothers Building	RB-12/ 13,	Rattan Street, Satsing Shivan Street, Karachi	Architectural Value

8/3/16

86.	Bhojraj Building	RB-10/ 1,	Babar (Ramchandra Temple) Road, Tirathdas Das Road, Karachi	Architectural Value
87.	Shikarpuri Mansion (Ceasor Building)	RB-10/ 8,	Assanmal Ojha Road, Gidumal Lekhraj Road	Architectural Value
88.	Darul-Ishaat (Tayyab Ali) Building	RB-10/ 9,	Babar (Ramchandra Temple) Road, Assanmal Ojha Road, Karachi	Architectural Value
89.	Hassan Ali (Lekhraj) Building	RB-10/ 18,	Babar (Ramchandra Temple) Road, Gidumal Lekhraj Road, Karachi	Architectural Value
90.	Bholchund Zehra Building	RB-10/ 24,	Robson Road, Gidumal Lekhraj Road, Karachi	Architectural Value
91.	Thakurdas Building (Zarina Manzil)	RB-10/ 23,	Robson Road, Gidumal Lekhraj Road, Karachi	Architectural Value
92.	Bhojaj Building	RB-10/ 21,	Babar (Ramchandra Temple) Road, Gidumal Lekhraj Road, Karachi	Architectural Value
93.	Sheikha Building	RB-10/ 10,	Babar (Ramchandra Temple) Road, Gidumal Lekhraj Road, Karachi	Architectural Value
94.	Ganga Ram Building	RB-10/ 11,	Gidumal Lekhraj Road, Assanmal Ojha Road, Karachi	Architectural Value
95.	Malkani Mansion	RB-10/ 12,	Gidumal Lekhraj Road, M. A. Jinnah (Bunder) Road, Karachi	Architectural Value
96.	Rehman Dental Clinic Building	RB-10/ 12A,	M. A. Jinnah (Bunder) Road, Babar (Ramchandra Temple) Road, Karachi	Architectural Value
97.	Azfar Mansion (Rehman Building)	RB-10/ 13,	M. A. Jinnah (Bunder) Road, Gidumal Lekhraj Road, Karachi	Architectural Value
98.	Thakurdas Building (Thakur Singh Building)	RB-10/ 14,	M. A. Jinnah (Bunder) Road, Karachi	Architectural Value
99.	Mukhi Wadhmal Building	RB-11/ 1A, 1,	M. A. Jinnah (Bunder) Road, Pahilraj Lilaram Road, Karachi	Architectural Value
100.	Government Veterinary Hospital (Richmond Crawford Dispensary)	RB-11/ 2/ 1,	M. A. Jinnah (Bunder) Road, Karachi	Architectural Value
101.	China Amersi Building	RB-12/ 14,	Rattan Street, Satsing Shivan Street, Karachi	Architectural Value
102.	Domed Structure	RB-12/ 14A,	Rattan Street, Satsing Shivan Street, Karachi	Architectural Value
103.	Qadeer Brothers Building	RB-12/ 13,	Rattan Street, Satsing Shivan Street, Karachi	Architectural Value

102
8/3/12

104

104.	Hotel Home (Lahori) Building	RB-12/ 13A,	Rattan Street, Satsing Shivan Street, Karachi	Architectural Value
105.	Mehmood Library (China Amersi)	RB-12/ 7,	Rattan Street, Satsing Shivan Street, Karachi	Architectural Value
106.	Silver House	RB-11/ 10/ 1,	Babar (Ramchandra Temple) Road, Karachi	Architectural Value
107.	Rehmat Building	RB-11/ 9,	Babar (Ramchandra Temple) Road, Karachi	Architectural Value
108.	Saeeda Manzil	RB-11/ 4,	Babar (Ramchandra Temple) Road, Karachi	Architectural Value

In accordance with Section 6(2) of the Sindh Cultural Heritage (Preservation) Act, 1994, any objection to the issuance of the notification should be addressed to the Government i.e. Culture, Tourism & Antiquities Department, Government of Sindh, within one month from the date of its publication.

Any intentional act to destroy, alter, deface and imperil the Protected Heritage or to build on or near the sites will be unlawful, and punishable under section 18 of the Sindh Cultural Heritage (Preservation) Act, 1994.

-GHULAM AKBAR LAGHARI-

Secretary to Govt. of Sindh

Karachi dated the 08th March, 2018

No.OSD/CHC/RBQ-01-49/2017

A copy is forwarded for information and necessary action to:-

1. The Chief Secretary, Sindh / Chairman Advisory Committee on Sindh Cultural Heritage.
2. The Chairman, Planning & Development Board, Govt. of Sindh.
3. The Chairman, Technical Committee on Sindh Cultural Heritage.
4. The Administrative Secretaries (All), Government of Sindh.
5. The Senior Member, Board of Revenue, Government of Sindh, with request not to partition above heritage properties, without prior approval of Advisory Committee.
6. The Commissioner, Karachi.
7. The Director General, Sindh Building Control Authority.
8. The Director General (Antiquities & Archaeology), CT&AD, Government of Sindh.
9. The Director (Heritage), CT&AD, Government of Sindh
10. All Members of Advisory / Technical Committee on Sindh Cultural Heritage.
11. The Administrator (SZ), Evacuee Trust Properties, Karachi.
12. The Chief Executive Officer, Cantonment Board, Karachi.
13. The Deputy Commissioner-South, Karachi.
14. The Superintendent, Sindh Government Printing Press, Government of Sindh, He is requested to supply 50 copies of the Sindh Government Gazette to this department for official use.
15. PS to Minister of Culture, Tourism & Antiquities Department Government of Sindh, Karachi.
16. The Owner / Occupant.
17. Notification File.

**SECTION OFFICER
(HERITAGE)**

For Secretary to Govt. of Sindh



ADDENDUM-01

105

GOVERNMENT OF SINDH
CULTURE, TOURISM &
ANTIQUITIES DEPARTMENT

NOTIFICATION

No. OSD/CHC/RBQ-01-49/2017: (Addendum-01) In exercise of the powers conferred by Sub-Section (1) of Section-6 of the Sindh Cultural Heritage (Preservation) Act, 1994, and on the recommendations of Advisory Committee on Sindh Cultural Heritage, the Culture, Tourism & Antiquities Department, Government of Sindh is pleased to declare the premises/buildings described below to be Protected Heritage within the meaning of the said Act.

(RAMBAGH QUARTER KARACHI)

S.NO.	NAME OF BUILDING	PLOT #	ADDRESS	REASON FOR ENLISTMENT AS HERITAGE
✓ 109.	Shams Manzil	RB-9/ 6,	Mohammad Bin Qasim (Burnes) Road;	Architectural Value
✓ 110.	Radio Pakistan Building	RB-11/ 1,	M.A. Jinnah (Bunder) Road;	Architectural Value
✓ 111.	Hamdard Matab Building	RB-6/81,	Rambagh Road	Architectural Value
✓ 112.	Dawakhana Hakim Ajmal Khan	RB-11/ 21/ 1,	M. A. Jinnah (Bunder) Road, Karachi	Architectural Value

In accordance with Section 6(2) of the Sindh Cultural Heritage (Preservation) Act, 1994, any objection to the issuance of the notification should be addressed to the Government i.e. Culture, Tourism & Antiquities Department, Government of Sindh, within one month from the date of its publication.

Any intentional act to destroy, alter, deface and imperil the Protected Heritage or to build on or near the sites will be unlawful, and punishable under section 18 of the Sindh Cultural Heritage (Preservation) Act, 1994.

-GHULAM AKBAR LAGHARI-

Secretary to Govt. of Sindh

Karachi dated the 14th May, 2018

No.OSD/CHC/RBQ-01-49/2017

A copy is forwarded for information and necessary action to:-

1. The Chief Secretary, Sindh / Chairman Advisory Committee on Sindh Cultural Heritage.
2. The Chairman, Planning & Development Board, Govt. of Sindh.
3. The Chairman, Technical Committee on Sindh Cultural Heritage.
4. The Administrative Secretaries (All), Government of Sindh.
5. The Senior Member, Board of Revenue, Government of Sindh, with request not to partition above heritage properties, without prior approval of Advisory Committee.
6. The Commissioner, Karachi.
7. The Director General, Sindh Building Control Authority.
8. The Director General (Antiquities & Archaeology), CT&AD, Government of Sindh.
9. The Director (Heritage), CT&AD, Government of Sindh.
10. All Members of Advisory / Technical Committee on Sindh Cultural Heritage.
11. The Administrator (SZ), Evacuee Trust Properties, Karachi.
12. The Chief Executive Officer, Cantonment Board, Karachi.
13. The Deputy Commissioner-South, Karachi.
14. The Superintendent, Sindh Government Printing Press, Government of Sindh, He is requested to supply 50 copies of the Sindh Government Gazette to this department for official use.
15. PS to Minister of Culture, Tourism & Antiquities Department Government of Sindh, Karachi.
16. PS to Secretary, CT&AD, Govt. of Sindh, Karachi.
17. The Owner / Occupant.
18. Notification File.

14/5/87
SECTION OFFICER
(HERITAGE)

For Secretary to Govt. of Sindh



ADDENDUM-2 (107)

GOVERNMENT OF SINDH
CULTURE, TOURISM &
ANTIQUITIES DEPARTMENT

NOTIFICATION

No. OSD/CHC/RBQ/01-49/2017:(ADDENDUM-2) In exercise of the powers conferred by Sub-Section (1) of Section-6 of the Sindh Cultural Heritage (Preservation) Act, 1994, and on the recommendations of Advisory Committee on Sindh Cultural Heritage, the Culture, Tourism & Antiquities Department, Government of Sindh is pleased to declare the premises/buildings described below to be Protected Heritage within the meaning of the said Act.

(RAMBAGH QUARTERS)

S.NO.	NAME OF BUILDING	PLOT #	ADDRESS	REASON FOR ENLISTMENT AS HERITAGE
113.	Sita Ram Building/ J.M.B Girls School	RB-9/ 3, 4,	Mohammad Bin Qasim (Burnes) Road	Architectural Value

In accordance with Section 6(2) of the Sindh Cultural Heritage (Preservation) Act, 1994, any objection to the issuance of the notification should be addressed to the Government i.e. Culture, Tourism & Antiquities Department, Government of Sindh, within one month from the date of its publication.

Any intentional act to destroy, alter, deface and imperil the Protected Heritage or to build on or near the sites will be unlawful, and punishable under section 18 of the Sindh Cultural Heritage (Preservation) Act, 1994.

-GHULAM AKBAR LAGHARI-

Secretary to Govt. of Sindh

Karachi dated the November. 2019

No. OSD/CHC/RBQ/01-49/2017 /1565

A copy is forwarded for information and necessary action to:-

1. The Chief Secretary, Sindh / Chairman Advisory Committee on Sindh Cultural Heritage.
2. The Chairman, Planning & Development Board, Govt. of Sindh.
3. The Chairman, Technical Committee on Sindh Cultural Heritage.
4. The Administrative Secretaries (All), Government of Sindh.
5. The Commissioner, Karachi.
6. The Senior Member, Board of Revenue, Government of Sindh, with request not to partition above heritage properties, without prior approval of Advisory Committee.
7. The Director General, Sindh Building Control Authority.

1 | Page (Heritage Buildings Notification, Rambagh Quarters)

108

8. The Director General (Antiquities & Archaeology), CT&AD, Government of Sindh.
9. The Director (Heritage), CT&AD, Government of Sindh
10. All Members of Advisory / Technical Committee on Sindh Cultural Heritage.
11. The Administrator (SZ), Evacuee Trust Properties, Karachi.
12. The Chief Executive Officer, Cantonment Board, Karachi.
13. The Deputy Commissioner-South, Karachi.
14. The Superintendent, Sindh Government Printing Press, Government of Sindh, He is requested to supply 50 copies of the Sindh Government Gazette to this department for official use.
15. PS to Minister of Culture, Tourism & Antiquities Department Government of Sindh, Karachi.
16. PS to Secretary, Culture, Tourism & Antiquities Department, Govt. of Sindh.
17. The Owner / Occupant.
18. Notification File.


SECTION OFFICER
(HERITAGE)

For Secretary to Govt. of Sindh




KARACHI HERITAGE BUILDINGS RE-SURVEY PROJECT






RAM BAGH QUARTER

**CULTURE, TOURISM AND ANTIQUITIES
DEPARTMENT
GOVERNMENT OF SINDH**




SHAHAB MANSION

	1.	IDENTIFICATION:		DAP-NED/000203	
		Site Name:		Shahab Mansion G +3 + 1	
		Other Names:			
	2.	LOCATION:			
		Address:		RB-9/17, Mohammad Bin Qasim (Burnes) Road, Jethmal Road.	
		Survey No.	Plot No.	Sheet No.	
		Coordinates	N-24'51.40'	E-066'59.876'	
		District/City/ Town/ Village:			
3.	OWNERSHIP:		Private ✓	Government	
	Name of Owner (s) UNKNOWN		PRIVATE		
4.	OCCUPANCY: Residential & Commercial				
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Roundels, Balconies, Cornices, Pilasters, Decorative Parapet.		
6.	MEASUREMENT:		Height- 100'	Length- 100'	Width- 100'
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition ✓ Needs repair
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		All the wires, hoardings and pipe fitting should be removed.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		22-12-2017		




HAROON MANSION

	1. IDENTIFICATION:	DAP-NED/000204		
	Site Name:	Haroon Mansion G + 1 + 1		
	Other Names:			
	2. LOCATION:			
	Address:	RB-9/16, Mohammad Bin Qasim (Burnes) Road, Jethmal Road.		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24°51.400'	E-067°00.908'	
District/City/ Town/ Village:				
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s)	PRIVATE UNKNOWN			
4. OCCUPANCY:	Residential & Commercial			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Balconies, Bossed Stone Masonry Decorative Parapet			
6. MEASUREMENT:	Height- 36'	Length- 100'	Width- 88'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8. STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP: 	PHOTOGRAPHS: 			
11. COMMENTS:	Extra additions on the roof-top should be removed.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	10-01-2018			




WASEEM MANSION

	1.	IDENTIFICATION:		DAP-NED/000205		
		Site Name:		Waseem Mansion G + 3 + 1		
		Other Names:				
	2.	LOCATION:				
		Address:		RB-9/15, Mohammad Bin Qasim (Burnes) Road, Jethmal Road.		
		Survey No.		Plot No.	Sheet No.	
		Coordinates		N-24'51.448'	E-067'00.893'	
		District/City/ Town/ Village:				
	3.	OWNERSHIP:		Private <input checked="" type="checkbox"/>	Government	
		Name of Owner (s) UNKNOWN		PRIVATE		
4.	OCCUPANCY:		Residential & Commercial			
5.	REASONS FOR PROTECTION:		Architectural Value: Cornices/Molding, Decorative Parapet			
6.	MEASUREMENT:		Height- 50'	Length- 100'	Width- 90'	
7.	CONSTRUCTION MATERIAL:		Sand stone			
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/> Needs repair	
9.	THEREAT(S):		Encroachments			
10.	LOCATION MAP:		PHOTOGRAPHS:			
						
11.	COMMENTS:		Alterations and encroachments should be removed.			
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.			
13.	NAME OF INVESTIGATOR:		Ejaz Elahi			
14.	DATE:		10-01-2018			

ROOMAN BUILDING


	1.	IDENTIFICATION:		DAP-NED/000206	
		Site Name:		Rooman Building. G + 3	
		Other Names:			
	2.	LOCATION:			
		Address:		RB-9/22, Tirathdas Road, Robson Road.	
		Survey No.		Plot No.	Sheet No.
	Coordinates		N-24'51.446'		E-067'00.885'
	District/City/ Town/ Village:				
	3.	OWNERSHIP:		Private <input checked="" type="checkbox"/>	Government
	Name of Owner (s)		PRIVATE UNKNOWN		
4.	OCCUPANCY: Residential & Commercial				
5.	REASONS FOR PROTECTION:		Architectural Value: Balconies, Cornices/Molding, Pilasters, Decorative Parapet		
6.	MEASUREMENT:		Height- Length- Width- 50' 118' 60'		
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		Electric wires, gadgets, sanitary fittings & etc. should be removed.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		09-01-2018		

SOBHRAJ CHETUMAL MATERNITY

	1.	IDENTIFICATION:		DAP-NED/000207	
		Site Name:		Sobhraj Chetumal Maternity G + 1	
		Other Names:			
	2.	LOCATION:			
		Address:		RB-10/26, Tirathdas Road, Robson Road.	
		Survey No.	Plot No.	Sheet No.	
		Coordinates	N-24'51.491'	E-067'00.986'	
		District/City/ Town/ Village:			
3.	OWNERSHIP:		Private	Government <input checked="" type="checkbox"/>	
	Name of Owner (s) PROVINCIAL GOVERNMENT		Government		
4.	OCCUPANCY: Owned				
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Cornices/Molding, Pilasters, Decorative Parapet, Entrance Portal		
6.	MEASUREMENT:		Height- 30'	Length- 83'	Width- 50'
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/> Needs repair
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		Building is in good state of maintenance.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social, historical and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		09-01-2018		

SINDH WILDLIFE BUILDING



NO PERMISSION


<p style="color: red; font-weight: bold; text-align: center;">NO PERMISSION</p>	1.	IDENTIFICATION:	DAP-NED/000211		
		Site Name:	Sindh Wildlife Building G + M		
		Other Names:			
	2.	LOCATION:			
		Address:	RB-1/3, Aiwan-e-Saddar (Havelock Road), Maulana Din M.Wafai (Strachan) Road		
		Survey No.	Plot No.	Sheet No.	
		Coordinates	N-24'51.491	E-067'00.986'	
		District/City/ Town/ Village:			
	3.	OWNERSHIP:	Private	Government <input checked="" type="checkbox"/>	
		Name of Owner (s) PROVINCIAL GOVERNMENT	GOVERNMENT		
4.	OCCUPANCY: Owned				
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Portal, Cornices/Molding, Pilasters, Decorative Parapet		
6.	MEASUREMENT:		Height-	Length-	Width-
7.	CONSTRUCTION MATERIAL:		Sand stone		
8	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/> Needs repair
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
		 <p style="font-size: small;">Location Map</p>		<p style="color: red; font-weight: bold; text-align: center;">NO PERMISSION</p>	
11.	COMMENTS:		Building is in good state of maintenance.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its historical and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		09-01-2018		

Y.M.C.A BUILDING






1. IDENTIFICATION:	DAP-NED/000212	
Site Name:	Y.M.C.A Building G + 1	
Other Names:		
2. LOCATION:		
Address:	RB-1/2, Aiwan-e-Saddar (Havelock Road, Maulana Din M. Wafai (Strachan) Road.	
Survey No.	Plot No.	Sheet No.
Coordinates	N-24'51.214'	E-067'01.592'
District/City/ Town/ Village:		
3. OWNERSHIP:	Private ✓	Government
Name of Owner (s) TRUST (MISSIONARY ORGANIZATION PROPERTY	PRIVATE	


4.	OCCUPANCY:	Owned			
5.	REASONS FOR PROTECTION:	Architectural Value: Arches, Arcade/Portico, Pilasters, Timer Pitched Roof, Bossed Stone Masonry			
6.	MEASUREMENT:	Height- 26'	Length- 112'	Width- 45'	
7.	CONSTRUCTION MATERIAL:	Sand stone			
8.	STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition √	Needs repair
9.	THEREAT(S):	Encroachments			
10.	LOCATION MAP:	PHOTOGRAPHS:			
					
11.	COMMENTS:	Building is in god state of maintenance.			
12.	RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social, historical and architectural value.			
13.	NAME OF INVESTIGATOR:	Ejaz Elahi			
14.	DATE:	09-01-2018			



NATIONAL ACADEMY OF PERFORMING ART (HINDU GYMKHANA)


	1.	IDENTIFICATION:	DAP-NED/000185		
		Site Name:	National Academy of Performing Art (Hindu Gymkhana) G + 1		
		Other Names:			
	2.	LOCATION:			
		Address:	RB-1/5, Sarwar Shaheed (Ingle) Road, Aiwan-e-Saddar (Havelock Road).		
		Survey No.	Plot No.	Sheet No.	
		Coordinates	N-24'51.132'	E-067'01.301'	
		District/City/ Town/ Village:			
3.	OWNERSHIP:	Private	Government <input checked="" type="checkbox"/>		
	Name of Owner (s) UNKNOWN	GOVERNMENT			
4.	OCCUPANCY: Rented				
5.	REASONS FOR PROTECTION:	Architectural Value: Arches, Arcade/Portico, Cornices/Molding, Dome, Pilasters, Decorative Parapet, Chatris, entrance Portal			
6.	MEASUREMENT:	Height- 20' (Gumbad – 30')	Length- 84'	Width- 56'	
7.	CONSTRUCTION MATERIAL:	Sand stone			
8.	STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9.	THEREAT(S):	Encroachments			
10.	LOCATION MAP:	PHOTOGRAPHS:			
					
11.	COMMENTS:	Building is in good state of maintenance.			
12.	RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social, historical and architectural value.			
13.	NAME OF INVESTIGATOR:	Ejaz Elahi			
14.	DATE:	09-01-2018			

MUSLIM GYMKHANA




	1.	IDENTIFICATION:		DAP-NED/000213		
		Site Name:		Muslim Gymkhana G + 1		
		Other Names:				
	2.	LOCATION:				
		Address:		RB-2, Dr. Ziauddin Ahmed (Kutchery) Road, Aiwan-e-Saddar (Havelock Road).		
		Survey No.	Plot No.	Sheet No.		
		Coordinates	N-24'51.150'	E-067'01.294'		
		District/City/ Town/ Village:				
	3.	OWNERSHIP:		Private <input checked="" type="checkbox"/>		Government
		Name of Owner (s)		PRIVATE TRUST		
4.	OCCUPANCY:		Owned			
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Arcade/ Portico, Cornices/Molding, Cupola, Pilasters			
6.	MEASUREMENT:		Height- 20'	Length- 94'	Width- 75'	
7.	CONSTRUCTION MATERIAL:		Sand stone			
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9.	THEREAT(S):		Encroachments			
10.	LOCATION MAP:		PHOTOGRAPHS:			
						
11.	COMMENTS:		Building is in good state of maintenance.			
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social, historical and architectural value.			
13.	NAME OF INVESTIGATOR:		Ejaz Elahi			
14.	DATE:		09-01-2018			

OLD STATE BANK BUILDING (VICTORIA MUSEUM)

NO PERMISSION


NO PERMISSION	1. IDENTIFICATION:	DAP-NED/000175		
	Site Name:	Old State Bank Building (Victoria Museum) G + M		
	Other Names:			
	2. LOCATION:			
	Address:	RB-2, Sarwar Shaheed (Ingle) Road.		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-	E-	
	District/City/ Town/ Village:			
	3. OWNERSHIP:	Private	Government <input checked="" type="checkbox"/>	
	Name of Owner (s) PROVINCIAL GOVERNMENT	GOVERNMENT		
4. OCCUPANCY:	Owned			
5. REASONS FOR PROTECTION:	Architectural Value: Pavement/ Walkways, Sculpture			
6. MEASUREMENT:	Height-	Length-	Width-	
7. CONSTRUCTION MATERIAL:	Sand stone			
8. STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:	PHOTOGRAPHS:			
 <p>Location Map</p>		<p>NO PERMISSION</p>		
11. COMMENTS:	The building is well maintained building			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social, historical and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	06-02-2018			

D.J SINDH GOVERNMENT SCIENCE COLLEGE EXTENSION

	1.	IDENTIFICATION:		DAP-NED/000214	
		Site Name:		D.J Sindh Government Science College Extension G + 2 +1	
		Other Names:			
	2.	LOCATION:			
		Address:		RB-2 Mohammad Bin Qasim (Burnes) Road, Shahrah-e-Kamal Ataturk (Kings Way)	
		Survey No.	Plot No.	Sheet No.	
		Coordinates	N-24'51.050	E-067'01.241	
		District/City/ Town/ Village:			
3.	OWNERSHIP:		Private	Government <input checked="" type="checkbox"/>	
	Name of Owner (s) PROVINCIAL GOVERNMENT		GOVERNMENT		
4.	OCCUPANCY:		Owned		
5.	REASONS FOR PROTECTION:		Architectural Value: Pilasters, Coupled Columns, Colonnaded/ Arcaded Verandah		
6.	MEASUREMENT:		Height- 36'	Length- 110'	Width- 78'
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/> Needs repair
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		The building is well maintained but extra additions need to be removed.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social, historical and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		10-01-2018		

N.E.D UNIVERSITY CITY CAMPUS

NO PERMISSION

<p style="color: red; font-weight: bold; text-align: center;">NO PERMISSION</p>	1.	IDENTIFICATION:	DAP-NED/000215		
		Site Name:	N.E.D University City Campus G + 1		
		Other Names:			
	2.	LOCATION:			
		Address:	RB-4, Mohammad Bin Qasim (Burnes) Road, Mulana Din M. Wafai (Strachan) Road.		
		Survey No.	Plot No.	Sheet No.	
		Coordinates	N-	E-	
		District/City/ Town/ Village:			
	3.	OWNERSHIP:	Private	Government ✓	
	Name of Owner (s) PROVINCIAL GOVERNMENT	GOVERNMENT			
4.	OCCUPANCY: Owned				
5.	REASONS FOR PROTECTION:	Architectural Value: Timber Roof, Entrance Portal, Bossed Stone Masonry, Coupled Columns, Chimney			
6.	MEASUREMENT:	Height-	Length-	Width-	
7.	CONSTRUCTION MATERIAL:	Sand stone			
8.	STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition ✓	Needs repair
9.	THEREAT(S):	Encroachments			
10.	LOCATION MAP:	PHOTOGRAPHS:			
	 <p style="font-size: small;">Location Map</p>	NO PERMISSION			
11.	COMMENTS:	Building is well maintained.			
12.	RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social, historical and architectural value.			
13.	NAME OF INVESTIGATOR:	Ejaz Elahi			
14.	DATE:	10-01-2018			




D.J SINDH COLLEGE (DEYARAM JETHMAL COLLAGE)






1.	IDENTIFICATION:	DAP-NED/000216		
	Site Name:	D.J Sindh College (Deyaram Jethmal Collage) G + 2		
	Other Names:			
2.	LOCATION:			
	Address:	RB-4/3 4, Dr. Ziauddin Ahmed (Kutchery) Road, Shahrah-e-Kamal Ataturk (Kings Way)		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.184	E-067'00.853	
	District/City/ Town/ Village:			
3.	OWNERSHIP:	Private	Government <input checked="" type="checkbox"/>	
	Name of Owner (s) PROVINCIAL GOVERNMENT	GOVERNMENT		

4.	OCCUPANCY:	Owned		
5.	REASONS FOR PROTECTION:	Architectural Value: Arches, Arcade/ portico, Pediments, Cornices/Molding, Cupola, Pilasters, Decorative Parapet, Entrance Portal		
6.	MEASUREMENT:	Height- 36'	Length- 398'	Width- 74'
7.	CONSTRUCTION MATERIAL:	Sand stone		
8.	STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/> Needs repair
9.	THEREAT(S):	Encroachments		
10.	LOCATION MAP:			
		PHOTOGRAPHS <div> </div>		
11.	COMMENTS:	Building is well maintained, but extra additions need to be removed.		
12.	RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social, historical and architectural value.		
13.	NAME OF INVESTIGATOR:	Ejaz Elahi		
14.	DATE:	10-01-2018		




GEETUMAL (GIDDU MALL) BUILDING

	1.	IDENTIFICATION:	DAP-NED/000217		
		Site Name:	Geetumal (Giddu Mall) Building G + 2		
		Other Names:			
	2.	LOCATION:			
		Address:	RB-3/26, Maulana Din M. Wafai (Strachan) Road. M.Binqasim (Burnes) Road.		
		Survey No.	Plot No.	Sheet No.	
		Coordinates	N-24.51'201	E-067'00.845	
		District/City/ Town/ Village:			
3.	OWNERSHIP:	Private <input checked="" type="checkbox"/>		Government	
	Name of Owner (s) MULTIPLE	PRIVATE			
4.	OCCUPANCY:	Residential & commercial			
5.	REASONS FOR PROTECTION:	Architectural Value: Cornices/Molding, Pilasters, Decorative Parapet			
6.	MEASUREMENT:	Height- 48'	Length- 60'	Width- 50'	
7.	CONSTRUCTION MATERIAL:	Sand stone			
8	STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9.	THEREAT(S):	Encroachments			
10.	LOCATION MAP:	PHOTOGRAPHS:			
					
11.	COMMENTS:	Building is well maintained, but extra additions need to be removed.			
12.	RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social and architectural value.			
13.	NAME OF INVESTIGATOR:	Ejaz Elahi			
14.	DATE:	11-01-2018			




KHAN ENTERPRISES / DMD TRUST BUILDING

	1.	IDENTIFICATION:	DAP-NED/000219		
		Site Name:	Khan Enterprises/ DMD Trust Building G + 1 + 1		
		Other Names:			
	2.	LOCATION:			
		Address:	RB-3/22/ 2, Maulana Din M. Wafai (Strachan) Road.		
		Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24.51'243		E-067'00.877	
	District/City/ Town/ Village:				
3.	OWNERSHIP:	Private <input checked="" type="checkbox"/>		Government	
	Name of Owner (s)	PRIVATE TRUST			
4.	OCCUPANCY: Rented				
5.	REASONS FOR PROTECTION:		Architectural Value: Cornices/Molding, Decorative Parapet		
6.	MEASUREMENT:		Height- 36'	Length- 100'	Width- 36'
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		Building is partially maintained and necessary repairs need to be required along with the removal of extra additions on roof top.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		11-01-2018		




DR.KHAN BUILDING

	1.	IDENTIFICATION:		DAP-NED/000220		
		Site Name:		Dr.Khan Building G		
		Other Names:				
	2.	LOCATION:				
		Address:		RB-3/18/ 1, Maulana Din Mohammad. Wafai (Strachan) Road.		
		Survey No.	Plot No.	Sheet No.		
		Coordinates	N-24.51'254	E-067'00.805		
		District/City/ Town/ Village:				
	3.	OWNERSHIP:		Private <input checked="" type="checkbox"/>	Government	
	Name of Owner (s)		PRIVATE UNKNOWN			
4.	OCCUPANCY:		Rented			
5.	REASONS FOR PROTECTION:		Architectural Value: Balconies, Cornices/Molding, Pilasters, Decorative Parapet, Pediments			
6.	MEASUREMENT:		Height- 140'	Length- 120'	Width- 86'	
7.	CONSTRUCTION MATERIAL:		Sand stone			
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition	Needs repair <input checked="" type="checkbox"/>
9.	THEREAT(S):		Encroachments			
10.	LOCATION MAP:		PHOTOGRAPHS:			
						
11.	COMMENTS:		Building is partially demolished and necessary repairs need to be required along with the removal of extra additions.			
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.			
13.	NAME OF INVESTIGATOR:		Ejaz Elahi			
14.	DATE:		11-01-2018			

SARNAGATI BUILDING

	1.	IDENTIFICATION:		DAP-NED/000221	
		Site Name:		Sarnagati Building G + 2	
		Other Names:			
	2.	LOCATION:			
		Address:		RB-5/71, Maulana Din Mohammad. Wafai (Strachan) Road, Arambagh Road.	
		Survey No.		Plot No.	Sheet No.
	Coordinates		N-24.51'251	E-067'00.804	
	District/City/ Town/ Village:				
	3.	OWNERSHIP:		Private <input checked="" type="checkbox"/>	Government
		Name of Owner (s)		PRIVATE	
		MULTIPLE			
4.	OCCUPANCY:		Rented		
5.	REASONS FOR PROTECTION:		Architectural Value:		
6.	MEASUREMENT:		Height- 48'	Length- 120'	Width- 90'
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:.		PHOTOGRAPHS:		
					
11.	COMMENTS:		Building is well maintained but extra additions need to be removed.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social, historical and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		11-01-2018		

P.K. SHAHANI BUILDING

	1.	IDENTIFICATION:	DAP-NED/000222	
		Site Name:	P.K. Shahani Building G + 2	
		Other Names:		
	2.	LOCATION:		
		Address:	RB-5/6, Hormusji Street, Dr. Ziauddin Ahmed (Kutchery) Road.	
		Survey No.	Plot No.	Sheet No.
	Coordinates	N-24.51'269	E-067'00.747	
	District/City/ Town/ Village:			
3.	OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government	
	Name of Owner (s)	PRIVATE UNKNOWN		
4.	OCCUPANCY:	Owned		
5.	REASONS FOR PROTECTION:	Architectural Value: Arches Pediments, Cornices/Molding, Pilasters, Decorative Parapet, Coupled Columns		
6.	MEASUREMENT:	Height- 36'	Length- 42'	Width- 30'
7.	CONSTRUCTION MATERIAL:	Sand stone		
8.	STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/> Needs repair
9.	THEREAT(S):	Encroachments		
10.	LOCATION MAP:	PHOTOGRAPHS:		
 <p style="text-align: center;">Location Map</p>				
11.	COMMENTS:	Removal of electric and other pipe-fittings.		
12.	RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social, historical and architectural value.		
13.	NAME OF INVESTIGATOR:	Ejaz Elahi		
14.	DATE:	12-01-2018		




BADRUDDIN BUILDING



1.	IDENTIFICATION:	DAP-NED/000223	
	Site Name:	Badruddin Building G + 1	
	Other Names:		
2.	LOCATION:		
	Address:	RB-5/5, Hormusji Street, Arambagh Road.	
	Survey No.	Plot No.	Sheet No.
	Coordinates	N-24.51'268	E-067'00.714
	District/City/ Town/ Village:		
3.	OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government
	Name of Owner (s) UNKNOWN	PRIVATE	

4.	OCCUPANCY:	Owned		
5.	REASONS FOR PROTECTION:	Architectural Value: Arches, Cornices/Molding, Pilasters, Decorative Parapet		
6.	MEASUREMENT:	Height- 12'	Length- 23'	Width- 107'
7.	CONSTRUCTION MATERIAL:	Sand stone		
8.	STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/> Needs repair
9.	THEREAT(S):	Encroachments		
10.	LOCATION MAP:			
		PHOTOGRAPHS:		
11.	COMMENTS:	Only the ground floor exists. Eclectic wires and other fittings should be removed.		
12.	RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its historical and architectural value.		
13.	NAME OF INVESTIGATOR:	Ejaz Elahi		
14.	DATE:	12-01-2018		




SITAKUNJ BUILDING

	1.	IDENTIFICATION:	DAP-NED/000224		
		Site Name:	Sitakunj Building G + 3 + 1		
		Other Names:			
	2.	LOCATION:			
		Address:	RB-5/3, Hormusji Street		
		Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24.51'282	E-067'00.709		
	District/City/ Town/ Village:				
	3.	OWNERSHIP:	Private	Government <input checked="" type="checkbox"/>	
		Name of Owner (s) PROVINCIAL GOVERNMENT	GOVERNMENT		
4.	OCCUPANCY: Owned				
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Pediments, Cornices/Molding, Pilasters, Decorative Parapet		
6.	MEASUREMENT:		Height- 60'	Length- 30'	Width- 20'
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/> Needs repair
9.	THEREAT(S):				
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		Electric wires, pipe-fittings and tin-sheds should be removed.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		12-01-2018		




SALIKA COMPANY BUILDING

	1. IDENTIFICATION:	DAP-NED/000225		
	Site Name:	Salika Company Building G		
	Other Names:			
	2. LOCATION:			
	Address:	RB-5/1, 3, Dr. Ziauddin Ahmed (Kutchery) Road		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24.51'275		E-067'00.712
	District/City/ Town/ Village:			
	3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government	
	Name of Owner (s)	PRIVATE UNKNOWN		
4. OCCUPANCY:	Owned			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Roundels, Cornices/Molding, Pilasters,			
6. MEASUREMENT:	Height- 20'	Length- 30'	Width- 30'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8. STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):				
10. LOCATION MAP:	PHOTOGRAPHS: <div style="display: flex; justify-content: space-around;">   </div>			
				
11. COMMENTS:	Old building has been completely renovated and altered.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	12-01-2018			




SEWA KUNJ HOSTAL

	1.	IDENTIFICATION:		DAP-NED/000226		
		Site Name:		Sewa Kunj Hostal G + 2		
		Other Names:				
	2.	LOCATION:				
		Address:		RB-5/10, Sharah-e-Liaquat (Frere Road)		
		Survey No.	Plot No.	Sheet No.		
		Coordinates	N-24.51'302	E-067'00.726		
		District/City/ Town/ Village:				
	3.	OWNERSHIP:		Private	Government	✓
		Name of Owner (s) Provincial Government		GOVERNMENT		
4.	OCCUPANCY:		Owned			
5.	REASONS FOR PROTECTION:		Architectural Value: Balconies, Cornices/Molding, Festoon			
6.	MEASUREMENT:		Height- 48'	Length- 120'	Width- 90'	
7.	CONSTRUCTION MATERIAL:		Sand stone			
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition	✓ Needs repair
9.	THEREAT(S):		Encroachments			
10.	LOCATION MAP:		PHOTOGRAPHS:			
						
11.	COMMENTS:		Building is in good condition but removal of the hoardings, air-conditioners and others fittings need to be required.			
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its historical and architectural value.			
13.	NAME OF INVESTIGATOR:		Ejaz Elahi			
14.	DATE:		15-01-2018			





MENDOZA BUILDING

	1.	IDENTIFICATION:		DAP-NED/000227		
		Site Name:		Mendoza Building G + 2		
		Other Names:				
	2.	LOCATION:				
		Address:		RB-5/11, Arambagh Road		
		Survey No.	Plot No.	Sheet No.		
		Coordinates	N-24.51'290	E-067'00.686		
		District/City/ Town/ Village:				
	3.	OWNERSHIP:		Private ✓	Government	
	Name of Owner (s)		PRIVATE UNKNOWN			
4.	OCCUPANCY:		Owned			
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet			
6.	MEASUREMENT:		Height- 48'	Length- 120'	Width- 60'	
7.	CONSTRUCTION MATERIAL:		Sand stone			
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition ✓ Needs repair	
9.	THEREAT(S):		Encroachments			
10.	LOCATION MAP:		PHOTOGRAPHS:			
						
11.	COMMENTS:		Partially maintained but the extra modern additions in front of ground floor need to be removed.			
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its historical and architectural value.			
13.	NAME OF INVESTIGATOR:		Ejaz Elahi			
14.	DATE:		15-01-2018			






RAZA LIBRARY BUILDING/ KASHIF MANZIL

	1.	IDENTIFICATION:		DAP-NED/000228	
		Site Name:		Raza Library Building/ Kashif Manzil G + 2 + 1	
		Other Names:			
	2.	LOCATION:			
		Address:		RB-7/20, Sharah-e-Liaquat (Frere Road)	
		Survey No.	Plot No.	Sheet No.	
	Coordinates		N-	E-	
	District/City/ Town/ Village:				
	3.	OWNERSHIP:		Private ✓	Government
		Name of Owner (s) UNKNOWN		PRIVATE	
4.	OCCUPANCY:		Owned		
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet, Festoon		
6.	MEASUREMENT:		Height- 48'	Length- 120'	Width- 60'
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition ✓ Needs repair
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		The extra modern additions on the roof-top and hoardings need to be removed.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its historical and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		-01-2018		

LUCKY CHAMBERS

	1. IDENTIFICATION:	DAP-NED/000229		
	Site Name:	Lucky Chambers G + 2 + 1		
	Other Names:			
	2. LOCATION:			
	Address:	RB-7/20, Sharah-e-Liaquat (Frere Road), Mohammad Bin Qasim (Burnes) Road		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51376	E-067'00.892	
	District/City/ Town/ Village:			
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s)	PRIVATE UNKNOWN			
4. OCCUPANCY:	Owned			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet, Rosettes			
6. MEASUREMENT:	Height- 36'	Length- 60'	Width- 60'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:	PHOTOGRAPHS: <div>    </div>			
11. COMMENTS:	The extra modern additions on the roof-top and hoardings need to be removed.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	16-01-2018			




MANZOOR SONS BUILDING

	1. IDENTIFICATION:	DAP-NED/000230		
	Site Name:	Manzoor Sons Building G + 2		
	Other Names:			
	2. LOCATION:			
	Address:			
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.377	E-067'00.915	
	District/City/ Town/ Village:			
3. OWNERSHIP:	Private ✓	Government		
Name of Owner (s)	PRIVATE UNKNOWN			
4. OCCUPANCY:	Owned			
5. REASONS FOR PROTECTION:	Architectural Value: Rosettes, Roundels, Balconies, Pilasters,			
6. MEASUREMENT:	Height- 36'	Length- 60'	Width- 60'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8. STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition ✓	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:	PHOTOGRAPHS:			
		  		
11. COMMENTS:	Ripping off the cement plaster and other fittings and relocation of the tree for restoring its visual integrity.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	16-01-2018			




JAMILA NIGHAT MATERNITY HOME (DHANI RAM SONS)

	1.	IDENTIFICATION:	DAP-NED/000231			
		Site Name:	Jamila Nighat Maternity Home (Dhani Ram Sons) G + 2 + 1			
		Other Names:				
	2.	LOCATION:				
		Address:	RB-6/116, Arambagh Road, Panjra Pure Road			
		Survey No.	Plot No.	Sheet No.		
	Coordinates	N-24'51.395		E-067'00.911		
	District/City/ Town/ Village:					
	3.	OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
		Name of Owner (s)	PRIVATE UNKNOWN			
4.	OCCUPANCY: Owned					
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet			
6.	MEASUREMENT:		Height- 48'	Length- 60'	Width- 30'	
7.	CONSTRUCTION MATERIAL:		Sand stone			
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/> Needs repair	
9.	THEREAT(S):		Encroachments			
10.	LOCATION MAP:		PHOTOGRAPHS:			
						
11.	COMMENTS:		Partially maintained. The extra additions on the roof-top, electric and others fittings need to be removed.			
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.			
13.	NAME OF INVESTIGATOR:		Ejaz Elahi			
14.	DATE:		18-01-2018			


HASAN MANZIL

	1.	IDENTIFICATION:		DAP-NED/000232	
		Site Name:		Hasan Manzil G + 3	
		Other Names:			
	2.	LOCATION:			
		Address:		RB-6/123, Arambagh Road, Sharah-e-Liaquat (Frere Road)	
		Survey No.		Plot No.	Sheet No.
	Coordinates		N-24°51.386		E-067°00.694
	District/City/ Town/ Village:				
	3.	OWNERSHIP:		Private ✓	Government
		Name of Owner (s)		PRIVATE TRUST	
4.	OCCUPANCY: Owned				
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet, Bossed Stone Masonry		
6.	MEASUREMENT:		Height-48'	Length-120'	Width-60'
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition ✓ Needs repair
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		Extensively shadowed by electric wires, hoardings and other fittings.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		18-01-2018		




LOG RAM BUILDING

	1.	IDENTIFICATION:		DAP-NED/000233	
		Site Name:		Log Ram Building G + 2	
		Other Names:			
	2.	LOCATION:			
		Address:		RB-6/121, 122, Arambagh Road, Panjra Pure Road	
	Survey No.		Plot No.	Sheet No.	
	Coordinates		N-24°51.302	E-067°00.725	
	District/City/ Town/ Village:				
	3.	OWNERSHIP:		Private ✓	Government
		Name of Owner (s) UNKNOWN		PRIVATE	
4.	OCCUPANCY: Owned				
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet		
6.	MEASUREMENT:		Height- 48'	Length- 100'	Width- 60'
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition ✓ Needs repair
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		Partially maintained. The modern additions on the roof-top and other fittings need to be removed.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		18-01-2018		




ZAINAB MANZIL

	1.	IDENTIFICATION:		DAP-NED/000234		
		Site Name:		Zainab Manzil G + 3		
		Other Names:				
	2.	LOCATION:				
		Address:		RB-6/98, Sharah-e-Liaquat (Frere Road), Hormusji Street		
		Survey No.	Plot No.	Sheet No.		
		Coordinates	N-24'51.319	E-067'00.714		
		District/City/ Town/ Village:				
	3.	OWNERSHIP:		Private <input checked="" type="checkbox"/>	Government	
		Name of Owner (s) MULTIPLE		PRIVATE		
4.	OCCUPANCY: Owned					
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet			
6.	MEASUREMENT:		Height- 48'	Length- 80'	Width- 74'	
7.	CONSTRUCTION MATERIAL:		Sand stone			
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition	Needs repair <input checked="" type="checkbox"/>
9.	THEREAT(S):		Encroachments			
10.	LOCATION MAP:		PHOTOGRAPHS:			
						
11.	COMMENTS:		Partially maintained. The building requires necessary repairs including removal of extra additions and electric wires.			
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.			
13.	NAME OF INVESTIGATOR:		Ejaz Elahi			
14.	DATE:		18-01-2018			






SAIFY ELECTRIC TRADING CO (NEW NAME IS ZAKERIA MANZIL)

	1.	IDENTIFICATION:	DAP-NED/000235		
		Site Name:	Saify Electric Trading Co (New Name is Zakeria Manzil) G + 2 + 1		
		Other Names:			
	2.	LOCATION:			
		Address:	RB-6/73, Sharah-e-Liaquat (Frere Road), Yousuf Street		
		Survey No.	Plot No.	Sheet No.	
		Coordinates	N-24'51.306	E-067'00.724	
District/City/ Town/ Village:					
	3.	OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government	
		Name of Owner (s)	PRIVATE MULTIPLE		
4.	OCCUPANCY:		Owned		
5.	REASONS FOR PROTECTION:		Architectural Value: Balconies, Pilasters, Decorative Parapet		
6.	MEASUREMENT:		Height- 48'	Length- 48'	Width- 30'
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/> Needs repair
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		Partially maintained. The modern additions on the roof-top, and other fittings need to be removed.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		18-01-2018		




MARKAZ-E-EHL-E-SUNNAT.

	1.	IDENTIFICATION:		DAP-NED/000236	
		Site Name:		Markaz-e-Ehl-e-Sunnat. G + 1 + 1	
		Other Names:			
	2.	LOCATION:			
		Address:		RB-6/45, Sharah-e-Liaquat (Frere Road), Yousuf Street	
		Survey No.	Plot No.	Sheet No.	
		Coordinates		N-24'51.288	E-067'00.691
		District/City/ Town/ Village:			
3.	OWNERSHIP:		Private ✓	Government	
	Name of Owner (s)		PRIVATE TRUST		
4.	OCCUPANCY: Owned				
5.	REASONS FOR PROTECTION:		Architectural Value: Balconies, Pilasters, Decorative Parapet		
6.	MEASUREMENT:		Height- 40'	Length- 60'	Width- 28'
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition ✓ Needs repair
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		Partially maintained. The modern additions on the roof-top, and other fittings need to be removed.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		19-01-2018		



SHAMS LIGHT HOUSE BUILDING

	1. IDENTIFICATION:	DAP-NED/000237		
	Site Name:	Shams Light House Building G + 2		
	Other Names:			
	2. LOCATION:			
	Address:	RB-6/15, Dr.Ziauddin Ahmed (Kutchery) Road, Masjid Street		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.296	E-067'00.638	
	District/City/ Town/ Village:			
	3. OWNERSHIP:	Private ✓	Government	
	Name of Owner (s)	PRIVATE UNKNOWN		
4. OCCUPANCY:	Owned			
5. REASONS FOR PROTECTION:	Architectural Value: Balconies			
6. MEASUREMENT:	Height- 36'	Length- 40'	Width- 40'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8. STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition ✓	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:	PHOTOGRAPHS: <div>    </div>			
 <p>Location Map</p>				
11. COMMENTS:	Partially maintained. The modern additions on the roof-top, and other fittings need to be removed.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	19-01-2018			




SADIK MANZIL

	1.	IDENTIFICATION:		DAP-NED/000238		
		Site Name:		Sadik Manzil G + 3		
		Other Names:				
	2.	LOCATION:				
		Address:		RB-6/107 Feroz Shah Road, Arambagh Road		
		Survey No.	Plot No.	Sheet No.		
		Coordinates	N-24'51.294	E-067'00.644		
		District/City/ Town/ Village:				
	3.	OWNERSHIP:		Private v	Government	
		Name of Owner (s) MULTIPLE		PRIVATE		
4.	OCCUPANCY: Owned					
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet			
6.	MEASUREMENT:		Height- 50'	Length- 100'	Width- 60'	
7.	CONSTRUCTION MATERIAL:		Sand stone			
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition v Needs repair	
9.	THEREAT(S):		Encroachments			
10.	LOCATION MAP:		PHOTOGRAPHS:			
						
11.	COMMENTS:		Partially maintained. The Building is well maintained but extra additions need to be removed.			
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.			
13.	NAME OF INVESTIGATOR:		Ejaz Elahi			
14.	DATE:		19-01-2018			




YOUSUF MANZIL

	1. IDENTIFICATION:	DAP-NED/000239		
	Site Name:	Yousuf Manzil G + 2 + 1		
	Other Names:			
	2. LOCATION:			
	Address:	RB-6/4, Abba Soomar Street		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.371	E-067'00.698	
District/City/ Town/ Village:				
3. OWNERSHIP:	Private ✓	Government		
Name of Owner (s)	PRIVATE MULTIPLE			
4. OCCUPANCY:	Owned			
5. REASONS FOR PROTECTION:	Architectural Value: Arches			
6. MEASUREMENT:	Height- 50'	Length- 00'	Width- 24'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8. STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition ✓	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:	PHOTOGRAPHS: <div>  <div>  </div> </div>			
11. COMMENTS:	Partially maintained. The modern additions on the roof-top, and other fittings need to be removed.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	19-01-2018			




UNKNOWN BUILDING

	1.	IDENTIFICATION:		DAP-NED/000240	
		Site Name:		G + 1	
		Other Names:			
	2.	LOCATION:			
	Address:		RB-6/3, Abba Soomar Street		
	Survey No.		Plot No.	Sheet No.	
	Coordinates		N-24'51.353	E-067'00.573	
	District/City/ Town/ Village:				
	3.	OWNERSHIP:		Private v	Government
		Name of Owner (s)		PRIVATE	
		UNKNOWN			
4.	OCCUPANCY: Rented				
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet Bossed Stone Masonry		
6.	MEASUREMENT:		Height- 36'	Length- 40'	Width- ---
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition v Needs repair
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		Partially maintained. The electric wires and other fittings need to be removed.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		19-01-2018		

ABU BAKAR SIDDIQUE MANZIL

	1. IDENTIFICATION:	DAP-NED/000241		
	Site Name:	Abu Bakar Siddique Manzil G + 2		
	Other Names:			
	2. LOCATION:			
	Address:	RB-6/1, M.A. Jinnah (Bunder) Road, Dr.Ziauddin Ahmed (Kutchery) Road		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.360	E-067'00.547	
	District/City/ Town/ Village:			
	3. OWNERSHIP:	Private v	Government	
	Name of Owner (s) UNKNOWN	PRIVATE		
4. OCCUPANCY:	Owned			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Rosette, Cornices/Molding, Pilasters,			
6. MEASUREMENT:	Height- 40'	Length- 40'	Width- 30'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition v	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:	PHOTOGRAPHS: <div>   </div>			
11. COMMENTS:	Partially maintained. Electric wires, hoardings and other fittings need to be removed.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	19-01-2018			







HAJI IBRAHIM BUILDING

	1.	IDENTIFICATION:		DAP-NED/000242		
		Site Name:		Haji Ibrahim Building G + 2		
		Other Names:				
	2.	LOCATION:				
		Address:		RB-6/1, M.A. Jinnah (Bunder) Road, Abba Soomar Street		
		Survey No.	Plot No.	Sheet No.		
		Coordinates		N-24'51.366 E-067'00.570		
		District/City/ Town/ Village:				
	3.	OWNERSHIP:		Private <input checked="" type="checkbox"/>	Government	
		Name of Owner (s)		PRIVATE UNKNOWN		
4.	OCCUPANCY:		Owned			
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Arcade/ Portico			
6.	MEASUREMENT:		Height- 36'	Length- 70'	Width- 45'	
7.	CONSTRUCTION MATERIAL:		Sand stone			
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9.	THEREAT(S):		Encroachments			
10.	LOCATION MAP:		PHOTOGRAPHS:			
						
11.	COMMENTS:		Partially maintained. Hoardings, electric wires and others fittings need to be removed.			
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.			
13.	NAME OF INVESTIGATOR:		Ejaz Elahi			
14.	DATE:		19-01-2018			







MOLLAI (BHAGWANI) MANSION

	1.	IDENTIFICATION:		DAP-NED/000243		
		Site Name:		Mollai (Bhagwani) Mansion G + 3		
		Other Names:				
	2.	LOCATION:				
		Address:		RB-6/18, M.A. Jinnah (Bunder) Road, Abba Soomar Street		
		Survey No.	Plot No.	Sheet No.		
		Coordinates		N-24'51.370	E-067'00.587	
		District/City/ Town/ Village:				
	3.	OWNERSHIP:		Private v	Government	
		Name of Owner (s) UNKNOWN		PRIVATE		
4.	OCCUPANCY: Rented					
5.	REASONS FOR PROTECTION:		Architectural Value: Balconies, Cornices/Molding, Pilasters, Decorative Parapet			
6.	MEASUREMENT:		Height- 60'	Length- 80'	Width- 60'	
7.	CONSTRUCTION MATERIAL:		Sand stone			
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition v Needs repair	
9.	THEREAT(S): Encroachments					
10.	LOCATION MAP:		PHOTOGRAPHS:			
						
11.	COMMENTS:		Partially maintained. Hoardings, electric fittings and other gadgets need to be removed.			
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.			
13.	NAME OF INVESTIGATOR:		Ejaz Elahi			
14.	DATE:		19-01-2018			







OPAL BUILDING

	1. IDENTIFICATION:	DAP-NED/000244		
	Site Name:	Opal Building G + 2 + 1		
	Other Names:			
	2. LOCATION:			
	Address:	RB-6/19, M.A. Jinnah (Bunder) Road, Abba Soomar Street		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.367	E-067'00.602	
	District/City/ Town/ Village:			
	3. OWNERSHIP:	Private v	Government	
	Name of Owner (s) UNKNOWN	PRIVATE		
4. OCCUPANCY:	Rented			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet, Pediments			
6. MEASUREMENT:	Height- 60'	Length- 80'	Width- 45'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition v	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:	PHOTOGRAPHS: <div>      </div>			
11. COMMENTS:	Well maintained. Hoardings, air conditioners and other fittings need to be removed.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social, historical and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	19-01-2018			





TALPUR BUILDING

	1. IDENTIFICATION:	DAP-NED/000246		
	Site Name:	Talpur Building G + 2 + 1		
	Other Names:			
	2. LOCATION:			
	Address:	RB-6/74, M.A. Jinnah (Bunder) Road		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.372	E-067'00.588	
	District/City/ Town/ Village:			
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s)	PRIVATE UNKNOWN			
4. OCCUPANCY:	Owned			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Pilasters, Decorative Parapet			
6. MEASUREMENT:	Height- 48'	Length- 60'	Width- 50'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:	PHOTOGRAPHS: <div>     </div>			
				
11. COMMENTS:	Partially maintained. Extra additions and other fittings need to be removed.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social, historical and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	22-01-2018			






GUL TRADING COMPANY BUILDING

	1. IDENTIFICATION:	DAP-NED/000247			
		Site Name:	(Gul Trading Company Building) New Name is Office House (Wassumal) G + 2 + 1		
		Other Names:			
	2. LOCATION:				
		Address:	RB-6/83, M.A. Jinnah (Bunder) Road		
		Survey No.	Plot No.	Sheet No.	
		Coordinates	N-024'51.417	E-067'00.658	
		District/City/ Town/ Village:			
	3. OWNERSHIP:	Private ✓	Government		
	Name of Owner (s)	PRIVATE			
	Muliple				
4. OCCUPANCY:	Owned				
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Balconies, Cornices/Molding, Pilasters				
6. MEASUREMENT:	Height- 48'	Length- 70'	Width- 62'		
7. CONSTRUCTION MATERIAL:	Sand stone				
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition ✓	Needs repair	
9. THEREAT(S):	Encroachments				
10. LOCATION MAP:	PHOTOGRAPHS:				
					
					
11. COMMENTS:	Partially maintained. Extra additions, hoardings and other fittings need to be removed.				
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social and architectural value.				
13. NAME OF INVESTIGATOR:	Ejaz Elahi				
14. DATE:	22-01-2018				





COFFEE HOUSE (WASSUMAL BUILDING)

	1. IDENTIFICATION:	DAP-NED/000248		
	Site Name:	Coffee House (Wassumal Building) G + 2		
	Other Names:			
	2. LOCATION:			
	Address:	RB-6/82, M.A. Jinnah (Bunder) Road		
Survey No.	Plot No.	Sheet No.		
Coordinates	N-024'51.417	E-067'00.658		
District/City/ Town/ Village:				
3. OWNERSHIP:	Private v	Government		
Name of Owner (s) UNKNOWN	PRIVATE			
4. OCCUPANCY:	Rented			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Balconies, Cornices/Molding, Pilasters			
6. MEASUREMENT:	Height- 48'	Length- 70'	Width- 62'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition v	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:	PHOTOGRAPHS:			
				
				
11. COMMENTS:	Partially maintained. Extra additions, hoardings and other fittings need to be removed.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social, historical and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	19-01-2018			




SAMI CHAMBERS

	1. IDENTIFICATION:	DAP-NED/000249		
	Site Name:	Sami Chambers G + 2		
	Other Names:			
	2. LOCATION:			
	Address:	RB-6/108, M.A. Jinnah (Bunder) Road, Aragbagh Road.		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.408		E-067'00.653
	District/City/ Town/ Village:			
	3. OWNERSHIP:	Private v	Government	
	Name of Owner (s) MULTIPLE	PRIVATE		
4. OCCUPANCY:	Rented			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Pediments, Cornices/Molding, Pilasters			
6. MEASUREMENT:	Height- 40'	Length- 68'	Width- 60'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition v	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:	PHOTOGRAPHS: <div>     </div>			
11. COMMENTS:	Partially maintained. Extra additions on the roof-top, hoardings, electric wires and others fittings need to be removed.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	22-01-2018			








AWAN LODGE

	1. IDENTIFICATION:	DAP-NED/000250		
	Site Name:	Awan Lodge G + 1 + 1		
	Other Names:			
	2. LOCATION:			
	Address:	RB-6/109, Arambagh Road, Panjra Pure Poad.		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.408	E-067'00.653	
	District/City/ Town/ Village:			
3. OWNERSHIP:	Private v	Government		
Name of Owner (s) UNKNOWN	PRIVATE			
4. OCCUPANCY:	Rented			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet			
6. MEASUREMENT:	Height- 40'	Length- 68'	Width- 60'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8. STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition	Needs repair v
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:	PHOTOGRAPHS: <div>    </div>			
11. COMMENTS:	Partially maintained. Removal of extra additions on the roof-top, hoardings, electric wires and others fittings.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	19-01-2018			




SINDH ZAMINDAR HOTEL

	1.	IDENTIFICATION:		DAP-NED/000251	
		Site Name:		Sindh Zamindar Hotel G + 2 + 1	
		Other Names:			
	2.	LOCATION:		RB-7/4, M.A. Jinnah (Bunder) Road, Bhojraj Road	
		Address:			
		Survey No.		Plot No.	Sheet No.
		Coordinates		N-24'51.331	E-067'00.520
		District/City/ Town/ Village:			
	3.	OWNERSHIP:		Private ✓	Government
		Name of Owner (s)		PRIVATE MULTIPLE	
4.	OCCUPANCY:		Owned		
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Decorative Parapet		
6.	MEASUREMENT:		Height- 40'	Length- 76'	Width- 76'
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition ✓ Needs repair
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		Building is in good state of maintenance but extra additions on the roof-top, hoardings, electric wires and others fittings need to be removed.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social, historical and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		23-01-2018		




ZUBAIDA MANSION

	1. IDENTIFICATION:		DAP-NED/000252	
	Site Name:		Zubaida Mansion G + 4	
	Other Names:			
	2. LOCATION:			
	Address:		RB-8/1/1,1/2, M.A. Jinnah (Bunder) Road, Robson Road	
	Survey No.		Plot No.	Sheet No.
	Coordinates		N-24'51.550	E-067'00.928
	District/City/ Town/ Village:			
	3. OWNERSHIP:		Private <input checked="" type="checkbox"/>	Government
	Name of Owner (s)		PRIVATE MULTIPLE	
4. OCCUPANCY:	Pugree			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet, Pediments, Coupled Columns, Festoon, Corbels			
6. MEASUREMENT:	Height- 65'	Length- 90'	Width- 50'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8. STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:	PHOTOGRAPHS: <div style="display: flex; flex-wrap: wrap;">      </div>			
				
11. COMMENTS:	Partially maintained. Un-necessary Electric equipment & wires, hoardings, and others fittings need to be removed.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	23-01-2018			

DOST MANZIL

	1.	IDENTIFICATION:		DAP-NED/000253	
		Site Name:		Dost Manzil G + 3	
		Other Names:			
	2.	LOCATION:			
		Address:		RB-8/4, Robson Road, Mohammad Bin Qasim (Burnes) Road.	
		Survey No.	Plot No.	Sheet No.	
		Coordinates	N-24'51..487	E-067'00.887	
		District/City/ Town/ Village:			
	3.	OWNERSHIP:		Private V	Government
		Name of Owner (s) MULTIPLE		PRIVATE	
4.	OCCUPANCY: Pugree				
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet		
6.	MEASUREMENT:		Height- 40'	Length- 110'	Width- 45'
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition ✓ Needs repair
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		Partially maintained. Extra additions on the roof-top, air conditioners, hoardings, electric wires and others fittings need to be removed		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		23-01-2018		



WADHUMAL DEUMAL PANCHAYAAT TRUST BUILDING

	1.	IDENTIFICATION:		DAP-NED/000254	
		Site Name:		Wadhupal Deumal Panchayat Trust Building G + 1	
		Other Names:			
	2.	LOCATION:			
		Address:		RB-9/7, Mohammad Bin Qasim (Burnes) Road	
		Survey No.	Plot No.	Sheet No.	
	Coordinates		N-24'51.476 E-067'00.884		
	District/City/ Town/ Village:				
	3.	OWNERSHIP:		Private v	Government
		Name of Owner (s)		PRIVATE TRUST	
4.	OCCUPANCY: Rented				
5.	REASONS FOR PROTECTION:		Architectural Value: Pilasters, Decorative Parapet		
6.	MEASUREMENT:		Height- 30'	Length- 50'	Width- 48'
7.	CONSTRUCTION MATERIAL:		Sand stone		
8	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition v Needs repair
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		Partially maintained. Modern additions on the roof-top and electric wires need to be removed.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social, historical and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		23-01-2018		







BHOJRAJ BUILDING

	1. IDENTIFICATION:	DAP-NED/000257		
	Site Name:	Bhojraj building G + 3		
	Other Names:			
	2. LOCATION:			
	Address:	RB-10/1, Babar (Ramchandra Temple) Road, Tirathdas Road		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.519	E-067'00.904	
	District/City/ Town/ Village:			
3. OWNERSHIP:	Private v	Government		
Name of Owner (s)		PRIVATE		
MULTIPLE				
4. OCCUPANCY:	Owned			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Broken Pediment,, Balconies, Cornices/Molding, Pilasters			
6. MEASUREMENT:	Height- 50'	Length- 64'	Width- 64'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:	PHOTOGRAPHS: <div>      </div>			
11. COMMENTS:	Partially maintained. Extra additions, electric wires and other fittings need to be removed.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	24-01-2018			




SHIKARPURI MANSION (CEASOR BUILDING)

	1.	IDENTIFICATION:		DAP-NED/000258	
		Site Name:		Shikarpuri Mansion (Ceasor Building) G + 2 + 1	
		Other Names:			
	2.	LOCATION:			
		Address:		RB-10/8, Assanmal Ojha Road, Gidumal Lekhraj Road.	
		Survey No.	Plot No.	Sheet No.	
		Coordinates	N-24'51.527	E-067'00.968	
District/City/ Town/ Village:					
	3.	OWNERSHIP:		Private ✓	Government
	Name of Owner (s)		PRIVATE MULTIPLE		
4.	OCCUPANCY:		Owned		
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet, Bossed Stone Masonry.		
6.	MEASUREMENT:		Height- 46'	Length- 70'	Width- 64'
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition ✓ Needs repair
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		Partially maintained. Extra additions, hoarding, electric wires and sanitary fittings need to be removed.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		24-01-2018		

DARUL-ISHAAT (TAYYAB ALI) BUILDING

	1. IDENTIFICATION:	DAP-NED/000259		
	Site Name:	Darul-Ishaat (Tayyab Ali) Building G + 2		
	Other Names:			
	2. LOCATION:			
	Address:	RB-10/9, Babar (Ramchandra Temple) Road, AssanmalOjha Road.		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.540	E-067'00.998	
	District/City/ Town/ Village:			
	3. OWNERSHIP:	Private V	Government	
	Name of Owner (s) MULTIPLE	PRIVATE		
4. OCCUPANCY:	Owned			
5. REASONS FOR PROTECTION:	Architectural Value:	Arches, Roundels, Balconies, Cornices/Molding, Pilasters		
6. MEASUREMENT:	Height-48'	Length-65'	Width-60'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8. STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:	PHOTOGRAPHS:			
				
				
11. COMMENTS:	Partially maintained. Modern constructions on the roof-top. Extensively over-lapped by hoardings, electric wires, fittings and plastering need to be removed.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social, historical and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	24-01-2018			





HASSAN ALI (LEKHRA) BUILDING

	1.	IDENTIFICATION:		DAP-NED/000260		
		Site Name:		Hassan Ali (Lekhra) Building G + 2 + 1		
		Other Names:				
	2.	LOCATION:				
		Address:		RB-10/18, Babar (Ramchandra Temple) Road, Gidumal Lekhraj Road,		
		Survey No.	Plot No.	Sheet No.		
		Coordinates	N-	E-		
		District/City/ Town/ Village:				
	3.	OWNERSHIP:		Private ✓	Government	
		Name of Owner (s) MULTIPLE		PRIVATE		
4.	OCCUPANCY: Owned					
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet, Festoon			
6.	MEASUREMENT:		Height-	Length-	Width	
7.	CONSTRUCTION MATERIAL:		Sand stone			
8	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition ✓ Needs repair	
9.	THEREAT(S):		Encroachments			
10.	LOCATION MAP:		PHOTOGRAPHS:			
						
11.	COMMENTS:		Extra construction on the roof-top and on other floors, electric wires and others fittings need to be removed.			
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.			
13.	NAME OF INVESTIGATOR:		Ejaz Elahi			
14.	DATE:		29-01-2018			




BHOLCHUND ZEHRA BUILDING

	1.	IDENTIFICATION:	DAP-NED/000261			
		Site Name:	Bholchund Zehra Building G + 2 + 1			
		Other Names:				
	2.	LOCATION:				
		Address:	RB-10/24, Robson Road, Gidumal Lekhraj Road.			
		Survey No.	Plot No.	Sheet No.		
		Coordinates	N-24'51.553	E-067'01.007		
		District/City/ Town/ Village:				
	3.	OWNERSHIP:	Private ✓	Government		
		Name of Owner (s) MULTIPLE	PRIVATE			
4.	OCCUPANCY: Owned					
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet			
6.	MEASUREMENT:		Height- 50'	Length- 110'	Width- 40'	
7.	CONSTRUCTION MATERIAL:		Sand stone			
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition ✓ Needs repair	
9.	THEREAT(S):		Encroachments			
10.	LOCATION MAP:		PHOTOGRAPHS:			
						
11.	COMMENTS:		Partially maintained. Extra construction on the roof-top, electric wires and others fittings need to be removed.			
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.			
13.	NAME OF INVESTIGATOR:		Ejaz Elahi			
14.	DATE:		29-01-2018			




THAKURDAS BUILDING (ZARINA MANZIL)

	1.	IDENTIFICATION:		DAP-NED/000262		
		Site Name:		Thakurdas Building (Zarina Manzil) G + 3 + 1		
		Other Names:				
	2.	LOCATION:				
		Address:		RB-10/23, Gidumal Lekhraj Road.		
		Survey No.	Plot No.	Sheet No.		
		Coordinates	N-24'51.553	E-067'01.004		
		District/City/ Town/ Village:				
	3.	OWNERSHIP:		Private <input checked="" type="checkbox"/>	Government	
		Name of Owner (s) MULTIPLE		PRIVATE		
4.	OCCUPANCY:		Owned			
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Balconies, Cornices/Molding, Pilasters			
6.	MEASUREMENT:		Height- 60'	Length- 60'	Width- 32'	
7.	CONSTRUCTION MATERIAL:		Sand stone			
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9.	THEREAT(S):		Encroachments			
10.	LOCATION MAP:		PHOTOGRAPHS:			
			 			
11.	COMMENTS:		Partially maintained. The original look has been concealed by cement plastering, which need to be removed.			
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.			
13.	NAME OF INVESTIGATOR:		Ejaz Elahi			
14.	DATE:		29-01-2018			




BHOJAJ BUILDING

	1.	IDENTIFICATION:		DAP-NED/000263	
		Site Name:		Bhojaj Building G + 2 + 2	
		Other Names:			
	2.	LOCATION:			
		Address:		RB-10/21, Babar (Ramchanra Temple) Road, Gidumal Lekhray Road.	
		Survey No.	Plot No.	Sheet No.	
	Coordinates		N-24'51.574		E-067'01.035
	District/City/ Town/ Village:				
	3.	OWNERSHIP:		Private V	Government
	Name of Owner (s) MULTIPLE		PRIVATE		
4.	OCCUPANCY: Owned				
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Pediments, Balconies, Cornices/Molding, Pilasters, Broken Pediment, Rosette		
6.	MEASUREMENT:		Height- 48'	Length- 40'	Width- 36'
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/> Needs repair
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		Partially maintained. Modern constructions on the roof-top and hoardings on the ground floor that enveloped it original look need to be removed.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		29-01-2018		




SHEIKHA BUILDING

	1.	IDENTIFICATION:	DAP-NED/000264		
		Site Name:	Sheikha Building G + 2		
		Other Names:			
	2.	LOCATION:			
		Address:	RB-10/10 Babar (Ramchandra Temple) Road, Gidumal Lekhray Road.		
		Survey No.	Plot No.	Sheet No.	
		Coordinates	N-24'51.616	E-067'01.027	
		District/City/ Town/ Village:			
	3.	OWNERSHIP:	Private ✓	Government	
		Name of Owner (s) UNKNOWN	PRIVATE		
4.	OCCUPANCY: Owned				
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Pediments, Balconies, Cornices/Molding, Pilasters, Decorative Parapet		
6.	MEASUREMENT:		Height- 48'	Length- 70'	Width- 40'
7.	CONSTRUCTION MATERIAL:		Sand stone		
8	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition ✓ Needs repair
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		Partially maintained. Extra additions and plastering need to be removed.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		25-01-2018		

GANGA RAM BUILDING

	1.	IDENTIFICATION:	DAP-NED/000265		
		Site Name:	Ganga Ram Building G + 2 + 1		
		Other Names:			
	2.	LOCATION:			
		Address:	RB-10/11, Gidumal Lekhraj Road, Assanmal Ojha Road.		
		Survey No.	Plot No.	Sheet No.	
		Coordinates	N-24'51.56+9	E-067'00.996	
		District/City/ Town/ Village:			
3.	OWNERSHIP:	Private ✓		Government	
	Name of Owner (s)	PRIVATE MULTIPLE			
4.	OCCUPANCY: Owned				
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Roundels, Pediments, Cornices/Molding, Pilasters, Decorative Parapet		
6.	MEASUREMENT:		Height- 40'	Length- 70'	Width- 30'
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition ✓ Needs repair
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		Partially maintained. Extra additions on the roof-top, and from the front need to be removed.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		25-01-2018		


MALKANI MANSION BUILDING

	1.	IDENTIFICATION:		DAP-NED/000266	
		Site Name:		Malkani Mansion Building G + 3	
		Other Names:			
	2.	LOCATION:			
		Address:		RB-10/12, Gudumal Lekhraj Road, M.A, Jinnah (Bunder) Road.	
		Survey No.	Plot No.	Sheet No.	
	Coordinates		N-24'51.600		E-067'00.900
	District/City/ Town/ Village:				
	3.	OWNERSHIP:		Private v	Government
	Name of Owner (s)		PRIVATE		
	MULTIPLE				
4.	OCCUPANCY: Owned				
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet		
6.	MEASUREMENT:		Height- 50'	Length- 70'	Width- 60'
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition v Needs repair
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		Partially maintained. Unnecessary plastering, hoardings and others fittings need to be removed.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		25-01-2018		




REHMAN DENTAL CLINIC BUILDING

	1. IDENTIFICATION:	DAP-NED/000267		
	Site Name:	Rehman Dental Clinic Building (old Shop Name G + 3)		
	Other Names:			
	2. LOCATION:			
	Address:	RB-10/12A, M.A. Jinnah (Bunder) Road, Babar Ramchandra Temple Road.		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.594	E-067'00.991	
District/City/ Town/ Village:				
3. OWNERSHIP:	Private v	Government		
Name of Owner (s)	PRIVATE UNKNOWN			
4. OCCUPANCY:	Owned			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Pediments, Cornices/Molding, Pilasters, Decorative Parapet			
6. MEASUREMENT:	Height-50'	Length-70'	Width-60'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8. STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition v	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:	PHOTOGRAPHS: <div>    </div>			
				
11. COMMENTS:	Partially maintained. Modern alterations & additions need to be removed.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	25-01-2018			




AZFAR MANSION

	1. IDENTIFICATION:	DAP-NED/000268		
	Site Name:	Azfar Mansion (Rehman Building) G + 4		
	Other Names:			
	2. LOCATION:			
	Address:	RB-10/13, M.A. Jinnah (Bunder) Road, Gidumal Lekhraj Road.		
	Survey No.	Plot No.	Sheet No.	
Coordinates	N-24'51.569	E-067'01.000		
District/City/ Town/ Village:				
3. OWNERSHIP:	Private v	Government		
Name of Owner (s)	PRIVATE UNKNOWN			
4. OCCUPANCY:	Pugree			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet, Pediments, Festoon, Corbels			
6. MEASUREMENT:	Height- 65'	Length- 70'	Width- 50'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8. STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition v	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:	PHOTOGRAPHS: <div style="display: flex; flex-wrap: wrap;">      </div>			
				
11. COMMENTS:	Partially maintained. Electric wires and others fittings need to be removed.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	24-01-2018			




THAKURDAS BUILDING

	1.	IDENTIFICATION:		DAP-NED/000269	
		Site Name:		Thakurdas Building (Thakur Singh Building) G + 3 + 1	
		Other Names:			
	2.	LOCATION:			
		Address:		RB-10/14, M.A. Jinnah (Bunder) Road.	
	Survey No.		Plot No.	Sheet No.	
	Coordinates		N-24'51.619	E-067'01.022	
	District/City/ Town/ Village:				
3.	OWNERSHIP:		Private ✓	Government	
	Name of Owner (s)		PRIVATE MULTIPLE		
4.	OCCUPANCY:		Owned		
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet		
6.	MEASUREMENT:		Height- 65'	Length- 70'	Width- 50'
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition ✓ Needs repair
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		Partially maintained. Extra additions, plastering, hoardings and other fittings need to be removed.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		24-01-2018		




MUKHI WADHUMAL BUILDING

	1.	IDENTIFICATION:		DAP-NED/000270		
		Site Name:		Mukhi Wadhmal Building G + 2		
		Other Names:				
	2.	LOCATION:				
		Address:		RB-11/1A, 1, 6/82, M.A. Jinnah (Bunder) Road, Pahilraj Lilaram Road.		
		Survey No.		Plot No.	Sheet No.	
		Coordinates		N-24°51.627	E-	
		District/City/ Town/ Village:				
	3.	OWNERSHIP:		Private V	Government	
		Name of Owner (s)		PRIVATE UNKNOWN		
4.	OCCUPANCY: Pugree					
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet			
6.	MEASUREMENT:		Height- 50'	Length- 80'	Width- 50'	
7.	CONSTRUCTION MATERIAL:		Sand stone			
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition v Needs repair	
9.	THEREAT(S):		Encroachments			
10.	LOCATION MAP:		PHOTOGRAPHS:			
						
11.	COMMENTS:		Partially maintained. Extensively enveloped by hoardings and defaced by extra modern additions that need to be removed.			
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.			
13.	NAME OF INVESTIGATOR:		Ejaz Elahi			
14.	DATE:		29-01-2018			




GOVERNMENT VETERINARY HOSPITAL

	1.	IDENTIFICATION:		DAP-NED/000271		
		Site Name:		Government Veterinary Hospital (Richmond Crawford Dispensary) G + 1		
		Other Names:				
	2.	LOCATION:				
		Address:		RB-11/2/1, M.A. Jinnah (Bunder) Road,		
		Survey No.	Plot No.	Sheet No.		
		Coordinates	N-24°51.6259	E-067°01.123		
		District/City/ Town/ Village:				
	3.	OWNERSHIP:		Private	Government <input checked="" type="checkbox"/>	
		Name of Owner (s) PROVINCIAL GOVERNMENT		GOVERNMENT		
4.	OCCUPANCY:		Owned			
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Pilasters, Cornices/Molding, Pilasters, Decorative Parapet, Colonnaded/ Arcaded Verandah			
6.	MEASUREMENT:		Height- 36'	Length- 56'	Width- 40'	
7.	CONSTRUCTION MATERIAL:		Sand stone			
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9.	THEREAT(S):		Encroachments			
10.	LOCATION MAP:		PHOTOGRAPHS:			
						
11.	COMMENTS:		Building is well maintained.			
12.	RECOMMENDATIONS		Building deserves to be declared as protected heritage due to its social, historical and architectural value.			
13.	NAME OF INVESTIGATOR:		Ejaz Elahi			
14.	DATE:		29-01-2018			




DAWAKHANA HAKIM AJMAL KHAN

	1. IDENTIFICATION:	DAP-NED/000272		
	Site Name:	Dawakhana Hakim Ajmal Khan G + 1 + 1		
	Other Names:			
	2. LOCATION:			
	Address:	RB-11/21/1, M.A. Jinnah (Bunder) Road,		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.691	E-067'01.154	
	District/City/ Town/ Village:			
3. OWNERSHIP:	Private ✓	Government		
	Name of Owner (s)	PRIVATE MULTIPLE		
4. OCCUPANCY:	Owned			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Decorative Parapet.			
6. MEASUREMENT:	Height- 28'	Length- 70'	Width- 30'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition ✓	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:	PHOTOGRAPHS: <div style="display: flex; justify-content: space-around;">   </div>			
				
11. COMMENTS:	Partially maintained but modern additions need to be removed.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social, historical and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	30-01-2018			




CHINA AMERSI BUILDING

	1.	IDENTIFICATION:		DAP-NED/000275	
		Site Name:		China Amersi Building G + 2 + 1	
		Other Names:			
	2.	LOCATION:			
		Address:		RB-12/14, Rattan Street, Satsing Shivan Street.	
		Survey No.	Plot No.	Sheet No.	
	Coordinates		N-24'51.641		E-067'01.228
	District/City/ Town/ Village:				
	3.	OWNERSHIP:		Private <input checked="" type="checkbox"/>	Government
	Name of Owner (s)		PRIVATE		
	MULTIPLE				
4.	OCCUPANCY: Owned				
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Cornices/Molding, Pilasters, Decorative Parapet, Timber Pitched Roof, Bossed Stone, Masonry		
6.	MEASUREMENT:		Height- 36'	Length- 70'	Width- 56'
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/> Needs repair
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		Partially maintained. The electric wires, hoardings and other fittings need to be removed.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social, historical and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		02-02-2018		
14.	DATE:		02-02-2018		




QADEER BROTHERS BUILDING

	1.	IDENTIFICATION:		DAP-NED/000277	
		Site Name:		Qadeer Brothers Building G + 1	
		Other Names:			
	2.	LOCATION:			
		Address:		RB-12/13, Rattan Street, Satsing Shivan Street.	
		Survey No.	Plot No.	Sheet No.	
	Coordinates		N-24°51.698		E-067°01.212
	District/City/ Town/ Village:				
	3.	OWNERSHIP:		Private v	Government
		Name of Owner (s)		PRIVATE TRUST	
4.	OCCUPANCY: Owned				
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet, Rose Windows		
6.	MEASUREMENT:		Height- 36'	Length- 60'	Width- 40'
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		Partially demolished. The building does require extensive repair and maintenance. The electric wires pipe-fittings need to be removed.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		02-02-2018		




HOTEL HOME (LAHORI) BUILDING

	1.	IDENTIFICATION:		DAP-NED/000278	
		Site Name:		Hotel Home (Lahori) Building. G + 2 + 1	
		Other Names:			
	2.	LOCATION:			
		Address:		RB-12/13A, Rattan Street, Satsing Shivan Street.	
		Survey No.	Plot No.	Sheet No.	
		Coordinates	N-24'51.695	E-067'01.221	
		District/City/ Town/ Village:			
3.	OWNERSHIP:		Private v	Government	
	Name of Owner (s)		PRIVATE MULTIPLE		
4.	OCCUPANCY: Pugree				
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet		
6.	MEASUREMENT:		Height- 36'	Length- 40'	Width- 50'
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition v Needs repair
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		Partially maintained. Extra additions, shad and hoardings need to be removed.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		02-02-2018		




MEHMOOD LIBRARY (CHINA AMERSI)

	1.	IDENTIFICATION:	DAP-NED/000279		
		Site Name:	Mehmood Library (China Amersi) G + 1 + 1		
		Other Names:			
	2.	LOCATION:			
		Address:	RB-12/7, Rattan Street.		
		Survey No.	Plot No.	Sheet No.	
		Coordinates	N-24'51.684	E-067'01.219	
		District/City/ Town/ Village:			
	3.	OWNERSHIP:	Private ✓	Government	
	Name of Owner (s)		PRIVATE UNKNOWN		
4.	OCCUPANCY:		Rented		
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Cornices/Molding, Pilasters, Decorative Parapet, Courtyard		
6.	MEASUREMENT:		Height- 36'	Length- 40'	Width- 55'
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition Needs repair ✓
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		Partially maintained. The building does require necessary repairs but extra additions, plastering, hoardings, sanitary pipe-fittings and electric wires need to be removed.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		02-02-2018		




SILVER HOUSE

	1.	IDENTIFICATION:		DAP-NED/000280	
		Site Name:		Silver House. G + 1	
		Other Names:			
	2.	LOCATION:			
		Address:		RB-11/10/1, Babar (Ramchandra Temple) Road	
		Survey No.		Plot No.	Sheet No.
		Coordinates		N-24'51.601	E-067'01.140
	District/City/ Town/ Village:				
	3.	OWNERSHIP:		Private ✓	Government
		Name of Owner (s)		PRIVATE	
		MULTIPLE			
4.	OCCUPANCY: Owned				
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Cornices/Molding, Pilasters, Decorative Parapet		
6.	MEASUREMENT:		Height- 36'	Length- 70'	Width- 67'
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition ✓ Needs repair
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		Partially demolished, rest of it is well maintained. The extra plastering, hoardings and electric wires need to be removed.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		31-01-2018		




REHMAT BUILDING

	1. IDENTIFICATION:	DAP-NED/000281		
	Site Name:	Rehmat Building G + 1 + 1		
	Other Names:			
	2. LOCATION:			
	Address:	RB-11/9, Babar (Ramchandra Temple) Road.		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.600		E-067'01.130
	District/City/ Town/ Village:			
	3. OWNERSHIP:	Private ✓	Government	
	Name of Owner (s)	PRIVATE UNKNOWN		
4. OCCUPANCY:	Owned			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet			
6. MEASUREMENT:	Height- 36'	Length- 50'	Width- 50'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition	Needs repair ✓
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:				
	PHOTOGRAPHS: 			
11. COMMENTS:	Partially maintained. The building does require extensive repair and maintenance.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	31-01-2018			




SAEEDA MANZIL

	1.	IDENTIFICATION:	DAP-NED/000284		
		Site Name:	Saeeda Manzil G + 2 + 1		
		Other Names:			
	2.	LOCATION:			
		Address:	RB-11/4, Babar (Ramchandra Temple) Road.		
		Survey No.	Plot No.	Sheet No.	
		Coordinates	N-24'51.582	E-067.01.086	
	District/City/ Town/ Village:				
3.	OWNERSHIP:	Private ✓	Government		
	Name of Owner (s)	PRIVATE MULTIPLE			
4.	OCCUPANCY:	Pugree			
5.	REASONS FOR PROTECTION:	Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet			
6.	MEASUREMENT:	Height- 40'	Length- 70'	Width- 26'	
7.	CONSTRUCTION MATERIAL:	Sand stone			
8.	STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition	Needs repair ✓
9.	THEREAT(S):	Encroachments			
10.	LOCATION MAP:	PHOTOGRAPHS:			
					
11.	COMMENTS:	Partially maintained but the building does require necessary repairs. The extra addition on top floor, plastering, hoardings and sanitary pipe-fittings need to be removed.			
12.	RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social and architectural value.			
13.	NAME OF INVESTIGATOR:	Ejaz Elahi			
14.	DATE:	31-01-2018			




OLD SHAHANI BUILDING 1

	1.	IDENTIFICATION:		DAP-NED/000778		
		Site Name:		Old Shahani Building 1 G + 2		
		Other Names:				
	2.	LOCATION:				
		Address:		RB-3/8/1, Teckchand Udhamdas Road.		
		Survey No.	Plot No.	Sheet No.		
		Coordinates	N-24°51.272	E-067°00.885		
		District/City/ Town/ Village:				
	3.	OWNERSHIP:		Private V	Government	
		Name of Owner (s) TRUST		PRIVATE		
4.	OCCUPANCY: Rented					
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Pilasters, ,Bossed Stone Masonry			
6.	MEASUREMENT:		Height- 50'	Length- 80'	Width- 30'	
7.	CONSTRUCTION MATERIAL:		Sand stone			
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable v	Good Condition	Needs repair
9.	THEREAT(S):		Encroachments			
10.	LOCATION MAP:		PHOTOGRAPHS:			
						
11.	COMMENTS:		Partially maintained. Building is in stable condition but also require necessary repairs.			
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.			
13.	NAME OF INVESTIGATOR:		Ejaz Elahi			
14.	DATE:		02-02-2018			



ANUBEHAR BUILDING

	1. IDENTIFICATION:	DAP-NED/000779		
	Site Name:	Anubehar Building G + 1 + 1		
	Other Names:			
	2. LOCATION:			
	Address:	RB--/23/1, D'Mello Road.		
	Survey No.	Plot No.	Sheet No.	
Coordinates	N-24'51.246		E-067'00.880	
District/City/ Town/ Village:				
3. OWNERSHIP:	Private V		Government	
Name of Owner (s)	PRIVATE			
UNKNOWN				
4. OCCUPANCY:	Owned			
5. REASONS FOR PROTECTION:	Architectural Value: Rosette., Decorative Parapet			
6. MEASUREMENT:	Height- 36'	Length- 50'	Width- 40'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8. STATUS / PRESENT CONDITION	Dilapidated	Stable V	Good Condition	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:				
10. PHOTOGRAPHS:				
11. COMMENTS:	Partially maintained. The extra additions on top floor, plastering, hoardings need to be removed			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	08-02-2018			





PREMKUNJ BUILDING

	1.	IDENTIFICATION:		DAP-NED/0002780	
		Site Name:		Premkunj Building G + 4	
		Other Names:			
	2.	LOCATION:			
		Address:		RB-3/23/2/2, Maulana Din Mohammad Wafai (Strachan) Road	
		Survey No.	Plot No.	Sheet No.	
		Coordinates	N-24'51.277	E-067'00.864	
District/City/ Town/ Village:					
	3.	OWNERSHIP:		Private ✓	Government
	Name of Owner (s)		PRIVATE MULTIPLE		
4.	OCCUPANCY:		Owned		
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Balconies, Pilasters, Decorative Parapet		
6.	MEASUREMENT:		Height- 50'	Length- 60'	Width- 50'
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable ✓	Good Condition Needs repair
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		Partially maintained. The extra additions, electric wires and plastering need to be removed.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		08-02-2018		




ALFALAH MANZIL

	1. IDENTIFICATION:	DAP-NED/000781		
	Site Name:	Alfalah Manzil G + 3 + 1		
	Other Names:			
	2. LOCATION:			
	Address:	RB-3/23/2/1, D'mello Road.		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.369	E-067'00.837	
	District/City/ Town/ Village:			
	3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government	
	Name of Owner (s) UNKNOWN	PRIVATE		
4. OCCUPANCY:	Rented			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Balconies, Cornices/Molding, Pilasters			
6. MEASUREMENT:	Height- 50'	Length- 65'	Width- 50'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable <input checked="" type="checkbox"/>	Good Condition	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:	PHOTOGRAPHS: 			
11. COMMENTS:	Partially maintained. The building is in stable condition but the extra additions, hoardings etc. need to be removed.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	08-02-2018			




NAVEEN MANSION

	1. IDENTIFICATION:	DAP-NED/000782		
	Site Name:	Naveen Mansion G + 3 + 1		
	Other Names:			
	2. LOCATION:			
	Address:	RB-6/86, Feroz Shah Street, Hormusji Street.		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.298	E-067'00.709	
	District/City/ Town/ Village:			
3. OWNERSHIP:	Private ✓	Government		
Name of Owner (s) MULTIPLE	PRIVATE			
4. OCCUPANCY:	Rented			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Roundels, Balconies, Pilasters, Decorative Parapet			
6. MEASUREMENT:	Height- 50'	Length- 60'	Width- 50'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable ✓	Good Condition	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:	PHOTOGRAPHS: <div>     </div>			
11. COMMENTS:	Partially maintained but the building also require necessary repairs. The extra additions on top floor, electric wires and hoardings need to be removed.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	08-2-2018			




PINJARA PURE BUILDING

	1.	IDENTIFICATION:		DAP-NED/000783		
		Site Name:		Pinjara Pure Building G + 2 + 1		
		Other Names:				
	2.	LOCATION:				
		Address:		RB-7/3, Panjara Pure Road, M.A. Jinnah (Bunder) Road.		
		Survey No.	Plot No.	Sheet No.		
		Coordinates	N-24°51.420	E-067°00.685		
		District/City/ Town/ Village:				
3.	OWNERSHIP:		Private <input checked="" type="checkbox"/>	Government		
	Name of Owner (s)		PRIVATE TRUST			
4.	OCCUPANCY:		Owned			
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet			
6.	MEASUREMENT:		Height- 48'	Length- 50'	Width- 40'	
7.	CONSTRUCTION MATERIAL:		Sand stone			
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable <input checked="" type="checkbox"/>	Good Condition	Needs repair
9.	THEREAT(S):		Encroachments			
10.	LOCATION MAP:		PHOTOGRAPHS:			
						
11.	COMMENTS:		Well maintained but the extra additions on top floor, plastering, hoardings and other fittings need to be removed.			
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.			
13.	NAME OF INVESTIGATOR:		Ejaz Elahi			
14.	DATE:		07-022018			




HAJI MANZOOR BUILDING

	1.	IDENTIFICATION:		DAP-NED/000784	
		Site Name:		Haji Manzoor Building G + 1 + 3	
		Other Names:			
	2.	LOCATION:			
		Address:		RB-7/9, Bhojraj Road, Ram Talao Road.	
		Survey No.	Plot No.	Sheet No.	
	Coordinates		N-24'51.440	E-067'00.949	
	District/City/ Town/ Village:				
3.	OWNERSHIP:		Private ✓	Government	
	Name of Owner (s) MULTIPLE		PRIVATE		
4.	OCCUPANCY: Pugree				
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters		
6.	MEASUREMENT:		Height- 110' 60'	Length- 80'	Width- 50'
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable ✓	Good Condition Needs repair
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		Partially maintained but extra additions & alterations need to be removed.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		07-02-2018		

AFUNDI MANZIL

	1.	IDENTIFICATION:		DAP-NED/000785	
		Site Name:		Afundi Manzil G + 3 + 1	
		Other Names:			
	2.	LOCATION:			
		Address:		RB-7/10/7, Chand Bellaram Road, Ram Talao Road.	
		Survey No.		Plot No.	Sheet No.
	Coordinates		N-24'51.395	E-067'00.799	
	District/City/ Town/ Village:				
	3.	OWNERSHIP:		Private ✓	Government
		Name of Owner (s) MULTIPLE		PRIVATE	
4.	OCCUPANCY: Pugree				
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Roundels, Balconies, Pilasters, Decorative Parapet		
6.	MEASUREMENT:		Height- 50'	Length- 90'	Width- 70'
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable ✓	Good Condition Needs repair
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		Partially maintained but electric wires and all the hoardings and extra additions & alterations need to be removed.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		07-02-2018		




KARACHI MANSION

	1. IDENTIFICATION:	DAP-NED/000786		
	Site Name:	Karachi Mansion G + 2 + M		
	Other Names:			
	2. LOCATION:			
	Address:	RB-7/12, M.A. Jinnah (Bunder) Road, Robson Road.		
	Survey No.	Plot No.	Sheet No.	
Coordinates	N-24'51.545	E-067'00.937		
District/City/ Town/ Village:				
3. OWNERSHIP:	Private ✓	Government		
Name of Owner (s)	PRIVATE UNKNOWN			
4. OCCUPANCY:	Owned			
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Pilasters, Decorative Parapet			
6. MEASUREMENT:	Height- 46'	Length- 50'	Width- 40'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8. STATUS / PRESENT CONDITION	Dilapidated	Stable ✓	Good Condition	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:				
		PHOTOGRAPHS: 		
11. COMMENTS:	Partially maintained but extra additions & alteration need to be removed.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	07-02-2018			





NAWAB MANZIL (RAMKRISHIN)

	1. IDENTIFICATION:	DAP-NED/000787		
	Site Name:	Nawab Manzil (Ramkrishin) G + 3 + 1		
	Other Names:			
	2. LOCATION:			
	Address:	RB-7/20C, Shahrah-e-Liaquat (Frere Road, Roop Chand Bellaram Road.		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.476	E-067'00.818	
	District/City/ Town/ Village:			
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s)	PRIVATE UNKNOWN			
4. OCCUPANCY:	Owned			
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Decorative Parapet			
6. MEASUREMENT:	Height- 48'	Length- 65'	Width- 60'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8. STATUS / PRESENT CONDITION	Dilapidated	Stable <input checked="" type="checkbox"/>	Good Condition	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:	<div style="display: flex;"> <div style="flex: 1;">  </div> <div style="flex: 1;"> PHOTOGRAPHS: <div style="display: grid; grid-template-columns: 1fr 1fr; gap: 5px;">     </div> </div> </div>			
11. COMMENTS:	Partially maintained but electric wires and all the hoardings and extra additions on top need to be removed.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	07-02-2018			




KHAN MANSION

	1.	IDENTIFICATION:		DAP-NED/000788		
		Site Name:		Khan Mansion G + 2		
		Other Names:				
	2.	LOCATION:				
		Address:		RB-7/22, Sunder Das Road, Bhojraj Road.		
		Survey No.	Plot No.	Sheet No.		
		Coordinates	N-24'51.383	E-067'00.767		
	District/City/ Town/ Village:					
3.	OWNERSHIP:		Private v	Government		
	Name of Owner (s)		PRIVATE UNKNOWN			
4.	OCCUPANCY:		Owned			
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet			
6.	MEASUREMENT:		Height- 50'	Length- 60'	Width- 50'	
7.	CONSTRUCTION MATERIAL:		Sand stone			
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable v	Good Condition	Needs repair
9.	THEREAT(S):		Encroachments			
10.	LOCATION MAP:		PHOTOGRAPHS:			
						
11.	COMMENTS:		Partially maintained but electric wires and hoardings need to be removed.			
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.			
13.	NAME OF INVESTIGATOR:		Ejaz Elahi			
14.	DATE:		07-02-2018			




KB NOORI BUILDING

	1. IDENTIFICATION:	DAP-NED/000789		
	Site Name:	KB Noori Building G + 3 + 1		
	Other Names:			
	2. LOCATION:			
	Address:	RB-8/7/2/1, M.A. Jinnah (Bunder) Road, Mohammad Bin Qasim (Burnes) Road		
	Survey No.	Plot No.	Sheet No.	
Coordinates	N-24°51.545	E-067°00.937		
District/City/ Town/ Village:				
3. OWNERSHIP:	Private v	Government		
Name of Owner (s) MULTIPLE	PRIVATE			
4. OCCUPANCY:	Pugree			
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Cornices/Molding, Pilasters			
6. MEASUREMENT:	Height- 48'	Length- 60'	Width- 40'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8. STATUS / PRESENT CONDITION	Dilapidated	Stable v	Good Condition	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:	PHOTOGRAPHS: <div>    </div>			
11. COMMENTS:	Partially maintained. Electric wires, hoardings and extra addition on top need to be removed to bring back its original look.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	07-02-2018			




SUGAN MANSION

	1.	IDENTIFICATION:		DAP-NED/000790		
		Site Name:		Sugan Mansion		
		Other Names:				
	2.	LOCATION:				
		Address:		RB-9/2/1, 2/2, 2/3, Mohammad Bin Qasim (Burnes) Road		
		Survey No.	Plot No.	Sheet No.		
		Coordinates	N-24'51.588	E-067'01.010		
		District/City/ Town/ Village:				
3.	OWNERSHIP:		Private <input checked="" type="checkbox"/>	Government		
	Name of Owner (s)		PRIVATE			
	MULTIPLE					
4.	OCCUPANCY:		Owned			
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet			
6.	MEASUREMENT:		Height- 48'	Length- 100'	Width- 60'	
7.	CONSTRUCTION MATERIAL:		Sand stone			
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable <input checked="" type="checkbox"/>	Good Condition	Needs repair
9.	THEREAT(S):		Encroachments			
10.	LOCATION MAP:		PHOTOGRAPHS:			
						
11.	COMMENTS:		Partially maintained but electric wires, hoardings and extra additions & alterations need to be removed to bring back its original look.			
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.			
13.	NAME OF INVESTIGATOR:		Ejaz Elahi			
14.	DATE:		01-02-2018			






SHAMS MANZIL

	1.	IDENTIFICATION:		DAP-NED/000791	
		Site Name:		Shams Manzil G + 3 + 1	
		Other Names:			
	2.	LOCATION:			
		Address:		RB-9/6, Mohammad Bin Qasim (Bunder) Road.	
		Survey No.	Plot No.	Sheet No.	
		Coordinates	N-24'51.531	E-067'00.916	
	District/City/ Town/ Village:				
	3.	OWNERSHIP:		Private ✓	Government
		Name of Owner (s) UNKNOWN		PRIVATE	
4.	OCCUPANCY: Pugree				
5.	REASONS FOR PROTECTION:		Architectural Value: Roundels, Balconies, Pilasters, Festoon		
6.	MEASUREMENT:		Height- 48'	Length- 80'	Width- 70'
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable ✓	Good Condition Needs repair
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		Partially maintained but electric wires, hoardings, extra additions & alterations need to be removed to bring back its original look.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		01-02-2018		




SAHELI MANSION

	1.	IDENTIFICATION:		DAP-NED/000792		
		Site Name:		Saheli Mansion G + 3		
		Other Names:				
	2.	LOCATION:				
		Address:		RB-9/13 Mohammad Bin Qasim (Burnes) Road, Robsan Road.		
		Survey No.	Plot No.	Sheet No.		
		Coordinates		N-24°51.495	E-067°00.898	
		District/City/ Town/ Village:				
3.	OWNERSHIP:		Private V	Government		
	Name of Owner (s) MULTIPLE		PRIVATE			
4.	OCCUPANCY:		Pugree			
5.	REASONS FOR PROTECTION:		Architectural Value: Balconies, Pilasters, Decorative Parapet			
6.	MEASUREMENT:		Height- 50'	Length- 120'	Width- 90'	
7.	CONSTRUCTION MATERIAL:		Sand stone			
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable <input checked="" type="checkbox"/>	Good Condition	Needs repair
9.	THEREAT(S):		Encroachments			
10.	LOCATION MAP:		PHOTOGRAPHS:			
						
11.	COMMENTS:		Partially maintained but electric wires, hoardings, extra additions & alterations need to be removed to bring back its original look.			
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.			
13.	NAME OF INVESTIGATOR:		Ejaz Elahi			
14.	DATE:		01-02-2018			




JAMNADAS BUILDING

	1. IDENTIFICATION:	DAP-NED/000793		
	Site Name:	Jamnadas Building G + 1 + 1		
	Other Names:	Coffee House (Wassumal)		
	2. LOCATION:			
	Address:	RB-9/18, Jethamal Road, Jhamrai Road.		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24°51.486	E-067°00.892	
	District/City/ Town/ Village:			
3. OWNERSHIP:	Private V	Government		
	Name of Owner (s) MULTIPLE	PRIVATE		
4. OCCUPANCY:	Owned			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Pilasters			
6. MEASUREMENT:	Height- 48'	Length- 100'	Width- 80'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition	Needs repair V
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:	PHOTOGRAPHS: <div style="display: flex; flex-wrap: wrap;">     </div>			
11. COMMENTS:	Partially maintained. The building requires extensive repair works but also electric wires, hoardings extra additions & alterations need to be removed to bring back its original look.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	06-02-2018			




MOTI RAM BUILDING

	1.	IDENTIFICATION:		DAP-NED/000794	
		Site Name:		Moti Ram Building G + 1 + 1	
		Other Names:			
	2.	LOCATION:			
	Address:		RB-9/20, Jhamrai Road, Amil Road.		
	Survey No.		Plot No.	Sheet No.	
	Coordinates		N-24'51.431	E-067'00.941	
	District/City/ Town/ Village:				
	3.	OWNERSHIP:		Private v	Government
		Name of Owner (s) MULTIPLE		PRIVATE	
4.	OCCUPANCY: Owned				
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Balconies, Cornices/Molding		
6.	MEASUREMENT:		Height- 38'	Length- 70'	Width- 50'
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable v	Good Condition
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		Partially maintained but electric wires, hoardings, extra additions & alterations need to be removed.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		06-02-2018		






RAIS MANZIL

	1.	IDENTIFICATION:		DAP-NED/000797		
		Site Name:		Rais Manzil G + 3		
		Other Names:				
	2.	LOCATION:				
		Address:		RB-10/3, Tirathdas Road, Assanmal Ojha Road.		
		Survey No.		Plot No.	Sheet No.	
		Coordinates		N-24'51.559	E-067'00.968	
		District/City/ Town/ Village:				
3.	OWNERSHIP:		Private V	Government		
	Name of Owner (s)		PRIVATE MULTIPLE			
4.	OCCUPANCY:					Pugree
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet, Pilaster, Rosette			
6.	MEASUREMENT:		Height- 50'	Length- 70'	Width- 48'	
7.	CONSTRUCTION MATERIAL:		Sand stone			
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable v	Good Condition	Needs repair
9.	THEREAT(S):		Encroachments			
10.	LOCATION MAP:		PHOTOGRAPHS:			
						
11.	COMMENTS:		Partially maintained but electric wires, hoardings, extra additions & alterations need to be removed.			
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.			
13.	NAME OF INVESTIGATOR:		Ejaz Elahi			
14.	DATE:		24-01-2018			




WAZIR ALI BUILDING

	1.	IDENTIFICATION:		DAP-NED/000798	
		Site Name:		Wazir Ali Building	
		Other Names:			
	2.	LOCATION:			
		Address:		RB-10/4, Tirathdas Road, Assanmal Ojha Road.	
		Survey No.		Plot No.	Sheet No.
		Coordinates		N-24°51.538	E-067°00.974
		District/City/ Town/ Village:			
3.	OWNERSHIP:		Private <input checked="" type="checkbox"/>	Government	
	Name of Owner (s)		PRIVATE UNKNOWN		
4.	OCCUPANCY: Pugree				
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet		
6.	MEASUREMENT:		Height- 50'	Length- 75'	Width- 60'
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable <input checked="" type="checkbox"/>	Good Condition
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		Partially maintained but electric wires, hoardings, extra additions & alterations need to be removed.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		24-01-2018		




WAZIR ASHRAF BUILDING

	1. IDENTIFICATION:	DAP-NED/000799		
	Site Name:	Wazir Ashraf Building.		
	Other Names:			
	2. LOCATION:			
	Address:	RB-10/5/1, Tirathdas Road, Assanmal Ojha Road.		
	Survey No.	Plot No.	Sheet No.	
Coordinates	N-24'51.530	E-067'00.993		
District/City/ Town/ Village:				
3. OWNERSHIP:	Private v	Government		
Name of Owner (s)	PRIVATE			
MULTIPLE				
4. OCCUPANCY:	Pugree			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet			
6. MEASUREMENT:	Height- 50'	Length- 70'	Width- 60'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable v	Good Condition	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:	PHOTOGRAPHS: <div style="display: flex; flex-wrap: wrap;">     </div>			
11. COMMENTS:	Partially maintained but electric wires, hoardings, extra additions & alterations need to be removed.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	24-01-2018			

NEW LEKHRAJ

	1. IDENTIFICATION:	DAP-NED/000801		
	Site Name:	New Lekhraj Urdu Manzil		
	Other Names:			
	2. LOCATION:			
	Address:			
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.600	E-067'01.013	
District/City/ Town/ Village:				
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s)	PRIVATE			
MULTIPLE				
4. OCCUPANCY:	Owned			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet			
6. MEASUREMENT:	Height-60'	Length-40'	Width-50'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8. STATUS / PRESENT CONDITION	Dilapidated	Stable <input checked="" type="checkbox"/>	Good Condition	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:	PHOTOGRAPHS: 			
				
11. COMMENTS:	Partially demolished but electric wires, hoardings, extra additions & alterations need to be removed.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	01-01-2018			




OLD LEKHRAJ

	1.	IDENTIFICATION:		DAP-NED/000802		
		Site Name:		Old Lekhraj G + 2 + 1		
		Other Names:				
	2.	LOCATION:				
		Address:		RB-10/16, Gidumal Lekhraj Road		
		Survey No.	Plot No.	Sheet No.		
	Coordinates		N-24'51.596	E-067'01.016		
	District/City/ Town/ Village:					
3.	OWNERSHIP:		Private <input checked="" type="checkbox"/>	Government		
	Name of Owner (s) MULTIPLE		PRIVATE			
4.	OCCUPANCY:		Owned			
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet			
6.	MEASUREMENT:		Height- 50'	Length- 60'	Width- 40'	
7.	CONSTRUCTION MATERIAL:		Sand stone			
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable <input checked="" type="checkbox"/>	Good Condition	Needs repair
9.	THEREAT(S):		Encroachments			
10.	LOCATION MAP:		PHOTOGRAPHS:			
						
11.	COMMENTS:		Partially demolished but electric wires, hoardings, extra additions & alterations need to be removed.			
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.			
13.	NAME OF INVESTIGATOR:		Ejaz Elahi			
14.	DATE:		26-01-2018			

MUHAMMAD ALI BUILDING

	1.	IDENTIFICATION:		DAP-NED/000803	
		Site Name:		Muhammad Ali Building	
		Other Names:			
	2.	LOCATION:			
		Address:			
		Survey No.	Plot No.	Sheet No.	
		Coordinates	N-24'51.587	E-067'01.016	
		District/City/ Town/ Village:			
3.	OWNERSHIP:		Private <input checked="" type="checkbox"/>	Government	
	Name of Owner (s) MULTIPLE		PRIVATE		
4.	OCCUPANCY: Pugree				
5.	REASONS FOR PROTECTION:		Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet		
6.	MEASUREMENT:		Height- 46'	Length- 60'	Width- 44'
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.			Dilapidated	Stable <input checked="" type="checkbox"/>	Good Condition <input type="checkbox"/> Needs repair <input type="checkbox"/>
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		Partially maintained but electric wires, hoardings, extra additions & alterations need to be removed.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		26-01-2018		

MAMA PARSI BUILDING

	1. IDENTIFICATION:	DAP-NED/000804		
	Site Name:	Mama Parsi Building		
	Other Names:			
	2. LOCATION:			
	Address:			
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.580	E-067'01.021	
District/City/ Town/ Village:				
3. OWNERSHIP:	Private	Government <input checked="" type="checkbox"/>		
Name of Owner (s)	GOVERNMENT			
PROVINCIAL GOVERNMENT				
4. OCCUPANCY:	Owned			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet			
6. MEASUREMENT:	Height- 60'	Length- 62'	Width- 60'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8. STATUS / PRESENT CONDITION	Dilapidated	Stable <input checked="" type="checkbox"/>	Good Condition	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:	PHOTOGRAPHS:			
				
11. COMMENTS:	Partially maintained but electric wires, hoardings, extra additions & alterations need to be removed.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	26-01-2018			

BHOLCHUND BUILDING

	1. IDENTIFICATION:	DAP-NED/000805		
	Site Name:	Bholchund Building		
	Other Names:			
	2. LOCATION:			
	Address:			
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.576	E-067'01.037	
	District/City/ Town/ Village:			
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
Name of Owner (s)	PRIVATE			
MULTIPLE				
4. OCCUPANCY:	Owned			
5. REASONS FOR PROTECTION:	Architectural Value: Arches, Roundels, Balconies, Cornices/Molding, Pilasters, Decorative Parapet			
6. MEASUREMENT:	Height-48'	Length-70'	Width-42'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8. STATUS / PRESENT CONDITION	Dilapidated	Stable <input checked="" type="checkbox"/>	Good Condition	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:	PHOTOGRAPHS:			
	  			
11. COMMENTS:	Partially maintained but electric wires, hoardings, extra additions & alterations need to be removed.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	26-01-2018			




KALAVATI NIVASS






1.	IDENTIFICATION:	DAP-NED/000806	
	Site Name:	Kalavati Nivass G + 2 + 2	
	Other Names:		
2.	LOCATION:		
	Address:	RB-11/1A, 2, Mohan Road, Pahilraj Lilaram Road.	
	Survey No.	Plot No.	Sheet No.
	Coordinates	N-24°51.676	E-067°01.142
	District/City/ Town/ Village:		
3.	OWNERSHIP:	Private ✓	Government
	Name of Owner (s) MULTIPLE	PRIVATE	

4.	OCCUPANCY:	Owned		
5.	REASONS FOR PROTECTION:	Architectural Value: Roundels, Balconies, Pediments, Plasters		
6.	MEASUREMENT:	Height- 50'	Length- 70'	Width- 40'
7.	CONSTRUCTION MATERIAL:	Sand stone		
8.	STATUS / PRESENT CONDITION	Dilapidated	Stable ✓	Good Condition Needs repair
9.	THEREAT(S):	Encroachments		
10.	LOCATION MAP:			
		PHOTOGRAPHS:		
11.	COMMENTS:	Partially maintained but electric wires, hoardings, extra additions & alterations need to be removed.		
12.	RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social and architectural value.		
13.	NAME OF INVESTIGATOR:	Ejaz Elahi		
14.	DATE:	30-01-2018		




AHMED ALI, AKBER ALI BUILDING

	1. IDENTIFICATION:	DAP-NED/000807		
	Site Name:	Ahmed Ali, Akber Ali Building G + 2 + 1		
	Other Names:			
	2. LOCATION:			
	Address:	RB-11/1A, 3, Mohan Road, Pahilraj Lilaram Road		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.602	E-067.01.051	
	District/City/ Town/ Village:			
3. OWNERSHIP:	Private <input checked="" type="checkbox"/>	Government		
	Name of Owner (s) UNKNOWN	PRIVATE		
4. OCCUPANCY:	Pugree			
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Cornices/Molding, Pilasters, Coupled Columns			
6. MEASUREMENT:	Height- 48'	Length- 70'	Width- 53'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8. STATUS / PRESENT CONDITION	Dilapidated	Stable <input checked="" type="checkbox"/>	Good Condition	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:				
	PHOTOGRAPHS: 			
11. COMMENTS:	Partially demolished but electric wires, hoardings, extra additions & alterations need to be removed.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	30-01-2018			




ASNAND KHATORI BUILDING

	1.	IDENTIFICATION:		DAP-NED/000808		
		Site Name:		Asnand Khatori Building G + 2		
		Other Names:				
	2.	LOCATION:				
		Address:		RB-11/1A, 4, RB-11/1A, 3, Mohan Road, Pahilraj Lilaram Road		
		Survey No.		Plot No.	Sheet No.	
	Coordinates		N-24'51.601		E-067'01.051	
	District/City/ Town/ Village:					
3.	OWNERSHIP:		Private <input checked="" type="checkbox"/>		Government	
	Name of Owner (s)		PRIVATE			
	MULTIPLE					
4.	OCCUPANCY:		Owned			
5.	REASONS FOR PROTECTION:		Architectural Value: Balconies, Pediments, Cornices/Molding, Pilasters, Decorative Parapet, Coupled Columns			
6.	MEASUREMENT:		Height- 48'	Length- 70'	Width- 50'	
7.	CONSTRUCTION MATERIAL:		Sand stone			
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable <input checked="" type="checkbox"/>	Good Condition	Needs repair
9.	THEREAT(S):		Encroachments			
10.	LOCATION MAP:		PHOTOGRAPHS:			
						
11.	COMMENTS:		Partially demolished but electric wires, hoardings, extra additions & alterations need to be removed.			
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.			
13.	NAME OF INVESTIGATOR:		Ejaz Elahi			
14.	DATE:		30-01-2018			




AZIZ MEHEL

	1. IDENTIFICATION:	DAP-NED/000809		
	Site Name:	Aziz Mehel G + 2		
	Other Names:			
	2. LOCATION:			
	Address:	RB-11/1A, 5, RB-11/1A, 3, Mohan Road, Pahilraj Lilaram Road		
	Survey No.	Plot No.	Sheet No.	
Coordinates	N-24'51.603	E-067'01.047		
District/City/ Town/ Village:				
3. OWNERSHIP:	Private v	Government		
Name of Owner (s)	PRIVATE UNKNOWN			
4. OCCUPANCY:	Pugree			
5. REASONS FOR PROTECTION:	Architectural Value: Balconies, Pediments			
6. MEASUREMENT:	Height- 48'	Length- 70'	Width- 70'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8. STATUS / PRESENT CONDITION	Dilapidated	Stable v	Good Condition	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:				
	PHOTOGRAPHS: 			
11. COMMENTS:	Partially maintained but electric wires, hoardings, extra additions & alterations need to be removed.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	30-01-2018			

NARAYAN GOPAL BUILDING

	1.	IDENTIFICATION:		DAP-NED/000810	
		Site Name:		NARAYAN Gopal Building G + 2 + M + 1	
		Other Names:			
	2.	LOCATION:			
		Address:		RB-11/1C, Babar (Ramchandra Temple) Road, Pahilraj Lilaram Road	
		Survey No.		Plot No.	Sheet No.
	Coordinates		N-24'51.591		E-067'01.046
	District/City/ Town/ Village:				
3.	OWNERSHIP:		Private <input checked="" type="checkbox"/>		Government
	Name of Owner (s)		PRIVATE UNKNOWN		
4.	OCCUPANCY: Pugree				
5.	REASONS FOR PROTECTION:		Architectural Value: Balconies, Pilasters		
6.	MEASUREMENT:		Height-		Width-
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable <input checked="" type="checkbox"/>	Good Condition
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		Partially demolished but electric wires, hoardings, extra additions & alterations need to be removed.		
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		30-01-2018		







SHAKEEL MANSION (CHALI COMPOUND)

	1. IDENTIFICATION:	DAP-NED/000811		
	Site Name:	Shakeel Mansion (Chali Compound) G +1 + 1		
	Other Names:			
	2. LOCATION:			
	Address:	RB-11/6, 7, Babar (Ramchandra Temple) Road Gwali Lane No.1		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.591	E-067'01.079	
	District/City/ Town/ Village:			
3. OWNERSHIP:	Private	✓	Government	
Name of Owner (s)	PRIVATE			
	MULTIPLE			
4. OCCUPANCY:	Owned			
5. REASONS FOR PROTECTION:	Architectural Value: Arches,			
6. MEASUREMENT:	Height- 36'	Length- 70'	Width- 32'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8. STATUS / PRESENT CONDITION	Dilapidated	Stable	✓	Good Condition
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:				
	PHOTOGRAPHS: 			
11. COMMENTS:	Partially maintained but electric wires, hoardings, extra addition on top need to be removed.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	31-01-2018			




GOVERNMENT BOYS PRIMARY SCHOOL

	1.	IDENTIFICATION:		DAP-NED/000812		
		Site Name:		Government Boys Primary School G + 2 + 1		
		Other Names:				
	2.	LOCATION:				
		Address:		RB-11/12, Babar (Ramchandra Temple Road, Gwali Lane No.1		
		Survey No.	Plot No.	Sheet No.		
		Coordinates		N-24'51.611	E-067.01.170	
		District/City/ Town/ Village:				
	3.	OWNERSHIP:		Private	Government v	
		Name of Owner (s) PROVINCIAL GOVERNMENT		GOVERNMENT		
4.	OCCUPANCY:		Owned			
5.	REASONS FOR PROTECTION:		Architectural Value:			
6.	MEASUREMENT:		Height- 48'	Length- 62'	Width- 42'	
7.	CONSTRUCTION MATERIAL:		Sand stone			
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable v	Good Condition	Needs repair
9.	THEREAT(S):		Encroachments			
10.	LOCATION MAP:		PHOTOGRAPHS:			
						
11.	COMMENTS:		The building is partially maintained but electric wires, hoardings, extra additions & alterations need to be removed.			
12.	RECOMMENDATIONS		The building deserves to be declared as protected heritage due to its social and architectural value.			
13.	NAME OF INVESTIGATOR:		Ejaz Elahi			
14.	DATE:		31-01-2018			

RAMCHANDRA TEMPLE

	1. IDENTIFICATION:	DAP-NED/000813		
	Site Name:	Ramchandra Temple G		
	Other Names:			
	2. LOCATION:			
	Address:	RB-11, Next To Plot 59, Babar (Ramchandra Temple) Road		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.643	E-067'.01237	
	District/City/ Town/ Village:			
3. OWNERSHIP:	Private v	Government v		
Name of Owner (s)	GOVERNMENT			
PROVINCIAL				
GOVERNMENT				
4. OCCUPANCY:	Residential & Commercial			
5. REASONS FOR PROTECTION:	Architectural Value: Cornices/Molding, Dome, Pilasters, Decorative Parapet, Sculpture			
6. MEASUREMENT:	Height- 36'	Length- 38'	Width- 24'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable v	Good Condition	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:	PHOTOGRAPHS: <div>     </div>			
				
11. COMMENTS:	Partially demolished.			
12. RECOMMENDATIONS	The building deserves to be declared as protected heritage due to its social and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	31-01-2018			



BURNS GARDEN

	1. IDENTIFICATION:	DAP-NED/000814		
	Site Name:	Burns Garden		
	Other Names:			
	2. LOCATION:			
	Address:	RB-2, Strachan Road, Shahrah-e-Kamal Ataturk (Kings Way), Dr. Ziauddin Ahmed (Kutchery)		
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.203	E-067'01.064	
	District/City/ Town/ Village:			
3. OWNERSHIP:	Private	Government <input checked="" type="checkbox"/>		
Name of Owner (s)	GOVERNMENT			
Govt. of Sindh.				
4. OCCUPANCY:	- (Public Park)			
5. REASONS FOR PROTECTION:	Architectural Value: Lights/Poles, Pavements/ Walkways, Shrubs/trees, Benches, Walls & Fences, Sculpture			
6. MEASUREMENT:	Height- 60'	Length- 80'	Width- 45'	
7. CONSTRUCTION MATERIAL:	Sand stone			
8 STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>	Needs repair
9. THEREAT(S):	Encroachments			
10. LOCATION MAP:	PHOTOGRAPHS: <div style="display: flex; justify-content: space-around;">   </div>			
				
11. COMMENTS:	The Garden is well maintained by the Culture, Tourism & Antiquities Department, Govt. of Sindh.			
12. RECOMMENDATIONS	The Garden deserves to be declared as protected heritage due to its social, historical and architectural value.			
13. NAME OF INVESTIGATOR:	Ejaz Elahi			
14. DATE:	08-02-2018			




PAKISTAN CHOWK








1.	IDENTIFICATION:		DAP-NED/000815	
	Site Name:		Pakistan Chowk	
	Other Names:			
2.	LOCATION:		RB-5, Strachan Road, Dr. Ziauddin Ahmed (Kutchery) Road	
	Address:			
	Survey No.	Plot No.	Sheet No.	
	Coordinates	N-24'51.253	E-067'00.727	
	District/City/ Town/ Village:			
3.	OWNERSHIP:		Private	Government <input checked="" type="checkbox"/>
	Name of Owner (s) PROVINCIAL GOVERNMENT		GOVERNMENT	

4.	OCCUPANCY:	-		
5.	REASONS FOR PROTECTION:	Architectural Value: Shrubs/ Trees, Walls & Fences		
6.	MEASUREMENT:	Height-	Length- 90'	Width- 30'
7.	CONSTRUCTION MATERIAL:	Sand stone		
8.	STATUS / PRESENT CONDITION	Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/> Needs repair
9.	THEREAT(S):	Encroachments		
10.	LOCATION MAP:			
	PHOTOGRAPHS:			
11.	COMMENTS:	Completely renovated.		
12.	RECOMMENDATIONS	The Chowk deserves to be declared as protected heritage due to its social, historical and architectural value.		
13.	NAME OF INVESTIGATOR:	Ejaz Elahi		
14.	DATE:	08-02-2018		

ARAM BAGH PARK

	1.	IDENTIFICATION:	DAP-NED/000816		
		Site Name:	Aram Bagh Park		
		Other Names:			
	2.	LOCATION:			
		Address:	RB-7/23, Frere Road, Panjara Pure Road, Roop Chand Bellaram Road		
		Survey No.	Plot No.	Sheet No.	
		Coordinates	N-24'51.383	E-067'00.781	
		District/City/ Town/ Village:			
3.	OWNERSHIP:	Private	Government <input checked="" type="checkbox"/>		
	Name of Owner (s)	GOVERNMENT			
	PROVINCIAL GOVERNMENT				
4.	OCCUPANCY: -				
5.	REASONS FOR PROTECTION:		Architectural Value: Lights/ Poles, Pavements/ Walkways, Shrubs/Trees, Benches, Walls & Fences, Kids Play Land		
6.	MEASUREMENT:		Height-	Length-	Width-
7.	CONSTRUCTION MATERIAL:		Sand stone		
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition <input checked="" type="checkbox"/>
9.	THEREAT(S):		Encroachments		
10.	LOCATION MAP:		PHOTOGRAPHS:		
					
11.	COMMENTS:		The Park requires extensive repair and maintenance works.		
12.	RECOMMENDATIONS		The Park deserves to be declared as protected heritage due to its social, historical and architectural value.		
13.	NAME OF INVESTIGATOR:		Ejaz Elahi		
14.	DATE:		07-02-2018		

SABRI CHOWK

	1.	IDENTIFICATION:		DAP-NED/000817		
		Site Name:		Sabri Chowk		
		Other Names:				
	2.	LOCATION:				
		Address:		RB-9, M.A. Jinnah (Bunder) road, Mohammad Bin Qasim (Burnes) Road.		
		Survey No.	Plot No.	Sheet No.		
		Coordinates	N-24'51.681	E-067'01.213		
		District/City/ Town/ Village:				
	3.	OWNERSHIP:		Private	Government <input checked="" type="checkbox"/>	
		Name of Owner (s) PROVINCIAL GOVERNMENT		GOVERNMENT		
4.	OCCUPANCY: -					
5.	REASONS FOR PROTECTION:		Architectural Value: Pavement/ Walkways, Sculpture			
6.	MEASUREMENT:		Height-	Length-	Width-	
7.	CONSTRUCTION MATERIAL:		Sand stone			
8.	STATUS / PRESENT CONDITION		Dilapidated	Stable	Good Condition	Needs repair
9.	THEREAT(S):		Encroachments			
10.	LOCATION MAP:		PHOTOGRAPHS:			
			  			
11.	COMMENTS:		The Park requires extensive repair and maintenance works.			
12.	RECOMMENDATIONS		The Park deserves to be declared as protected heritage due to its social, historical and architectural value.			
13.	NAME OF INVESTIGATOR:		Ejaz Elahi			
14.	DATE:		06-02-2018			